

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | |
|---|---------------------------------|-------------------|
| Name of Company Chevron | Contact Larry Ridenour | |
| Address HCR 60 Box 423 Lovington, NM 88260 | Telephone No. 505-396-4414 x102 | |
| Facility Name Central Vacuum Unit Satellite 5 | Facility Type Production | |
| Surface Owner State of NM | Mineral Owner State of NM | Lease No. B1113-1 |


LOCATION OF RELEASE

| | | | | | | | | |
|---------------|-----------|---------------|------------|---------------|------------------|---------------|----------------|------------|
| Unit Letter F | Section 6 | Township 18-S | Range 35-E | Feet from the | North/South Line | Feet from the | East/West Line | County Lea |
|---------------|-----------|---------------|------------|---------------|------------------|---------------|----------------|------------|

Latitude 32deg 46min 49.53 sec Longitude 103 deg 29 sec 52.57 sec

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release produced water and oil | Volume of Release .5 bbl oil 9 bbl water | Volume Recovered 2 bbl |
| Source of Release trunkline | Date and Hour of Occurrence 11/4/06 1PM | Date and Hour of Discovery 11/4/06 2 PM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Pat Caperton | |
| By Whom? Larry Ridenour | Date and Hour 11/6/06 7:20 AM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Line failed in steel crossover piece going into transite line. Line was isolated, fluid on ground was picked up and line was bled down into vacuum truck. | | |
| Describe Area Affected and Cleanup Action Taken.* Approximately 600 sq ft. One call has been done so that contaminated soil may be removed. | | |



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|--------------------------|
| Signature: <i>Larry D Ridenour</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Larry D. Ridenour | Approved by District Supervisor: <i>[Signature]</i> | |
| Title: Operations Representative | Approval Date: 11-12-06 | Expiration Date: 2-18-07 |
| E-mail Address: LRidenour@Chevron.com | Conditions of Approval: | |
| Date: 11/6/06 Phone: 505-396-4414 x102 | Submit Final C-141 (ADD IRP) Attached <input type="checkbox"/> | |

* Attach Additional Sheets If Necessary

Facility - PACOG 31747149
Incident - PACOG 31747234
Application - PACOG 31747353 RP# 1118