


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Plains Pipeline, LP	Contact	Daniel Bryant
Address	P.O. Box 3119 - Midland, TX 79702	Telephone No.	(432) 686-1769
Facility Name	Tract 5 4" Gathering	Facility Type	Pipeline
Surface Owner	Millard Deck Estate	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter M (SW/SW)	Section 22	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-----------------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N 32.45722220° Longitude W 103.15888890°

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	4" steel gathering line	Date and Hour of Occurrence	11/07/2006 10:00	Date and Hour of Discovery	11/07/2006 10:35
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton			
By Whom?	Daniel Bryant	Date and Hour	11/08/2006 16:30		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

External corrosion caused a release of 10 bbls of crude oil on a 6" gathering line. Line was clamped to mitigate the release until a pipeline replacement could be made. The pressure of the line is 50 lbs and throughput on the pipeline is approximately 850 bbls per day. The gravity of the crude oil is 38. H₂S content is <10 ppm. Depth of the pipeline at the source of the release is approximately 5' bgs.

Describe Area Affected and Cleanup Action Taken.*

Impacted soil will be remediated per NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Daniel Bryant</i>		OIL CONSERVATION DIVISION	
Printed Name: Daniel Bryant		Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental R/C Specialist		Approval Date: 11.18.06	Expiration Date: 2.18.07
E-mail Address: dmbryant@paalp.com		Conditions of Approval: WTRC50'	Attached <input type="checkbox"/>
Date: 11/16/06 Phone: (432) 686-1769		SUBMIT FINAL C-141	

* Attach Additional Sheets If Necessary

Facility - FPAC0633335918
Incident n PAC0633336090

VERTICAL DELINEATION SUBMITTED
TO OGD w/ PLAN application

RP#1124
FPAC0633336260