


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Plains Pipeline	Contact Camille Reynolds
Address 3112 West US Hwy 82, Lovington, NM 88260	Telephone No. 505-441-0965
Facility Name EK Queen 6"	Facility Type 6" Steel Pipeline

Surface Owner State Land Office	Mineral Owner	Lease No.
---------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter L	Section 7	Township 18S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32° 45' 38.2" Longitude 103° 30' 13.5"

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 10 barrels	Volume Recovered 0 barrels
Source of Release 6" Steel Pipeline	Date and Hour of Occurrence 11/10/2006 @ 11:00	Date and Hour of Discovery 11/10/2006 @ 11:49
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Camille Reynolds	Date and Hour 11/10/2006 @ 15:55	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Internal corrosion of the 6" steel pipeline resulted in release of sweet crude oil. A line clamp was installed to mitigate the release. The line is a 6 inch steel transmission pipeline that produces approximately 430 barrels of crude oil per day. The pressure on the line is 120 psi and the gravity of the sweet crude oil is 40.2. The sweet crude has an H₂S content of <10 ppm. Line depth is approximately 6 inches below ground surface.

Describe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was 450 square feet.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Camille Reynolds</i>		OIL CONSERVATION DIVISION	
Printed Name: Camille Reynolds		Approved by District Supervisor: <i>[Signature]</i>	
Title: Remediation Coordinator	Approval Date: 11.18.06	Expiration Date: 2.18.07	
E-mail Address: cjreynolds@paalp.com	Conditions of Approval: SUBMIT FINAL C-141		Attached <input type="checkbox"/>
Date: 11/13/2006	Phone: 505-441-0965		

* Attach Additional Sheets If Necessary

Facility #PAC0633336435
Incident - #PAC0633336517

RP# 1125
application - #PAC0633336623