


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>XTO Energy</u>	Contact <u>Jerry Parker</u>
Address <u>P.O. Box 700 Eunice New Mexico</u>	Telephone No. <u>505-441-1628</u>
Facility Name <u>North Vacuum ABO-East #12</u>	Facility Type <u>Producing Oil Well</u>
Surface Owner <u>Edson Ranches</u>	Mineral Owner _____ Lease No. _____

LOCATION OF RELEASE API# 30025298830000

Unit Letter <u>E</u>	Section <u>18</u>	Township <u>T-17s</u>	Range <u>35-E</u>	Feet from the _____	North/South Line _____	Feet from the _____	East/West Line _____	County _____
----------------------	-------------------	-----------------------	-------------------	---------------------	------------------------	---------------------	----------------------	--------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>Produced water</u>	Volume of Release <u>20 BBLs</u>	Volume Recovered <u>15 BBLs</u>
Source of Release _____	Date and Hour of Occurrence _____	Date and Hour of Discovery <u>12-2-2006 4:00pm</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Part Caperton NMOCD</u>	
By Whom? <u>Guy Pearce</u>	Date and Hour <u>12-2-2006 4:30pm</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Flowline leaked produced water after freezing. Line thawed and spilled approx 20 bbls of produced water to the ground. 15 bbls of water was sucked up with a vacuum truck. land owner notified

Describe Area Affected and Cleanup Action Taken.*

Area approx 30' long just off location on East side of well. Phoenix Environmental is scraping contaminated soil up and putting it on plastic.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Guy Pearce</u>	Approved by District Supervisor: <u>Chris Williams</u>	
Printed Name: <u>Guy Pearce</u>	Approval Date: <u>12/1/06</u>	Expiration Date: _____
Title: <u>Production Foreman</u>	Conditions of Approval: _____ Attached <input type="checkbox"/>	
E-mail Address: <u>guy.pearce@xtocenergy.com</u>	Date: <u>12-3-2006</u> Phone: <u>505-441-1637</u>	

* Attach Additional Sheets If Necessary

Incident - n PAC0634554001
application - p PAC0634554092

RP#1139