.

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Fran	cis Dr., Santa	a Fe, NM 87505		Sa	anta Fe	e, NM 875	05				side of form
		1,***	Rele	ease Notific	cation	and Co	orrective A	ction			
						<b>OPERA</b>	FOR		itial Repor	t 🛛	Final Report
Name of Co	mpany O	ccidental Per	mian Lin	nited Partnershi	p (	Contact Steven M. Bishop					
Address 1017 West Stanolind Road, Hobbs, N.M. 88240						Telephone No. (505) 397-8251					
Facility Name South Hobbs Unit #225						Facility Type Production					
Surface Owner City of Hobbs Mineral Owner						r Lease No>					
Surface Ow	ner eny o	1110003					· · · ·		z H	6	
						N OF RE		<u>Ht</u>	1 -		02531211
Unit Letter	Section	Township /85	Range	Feet from the	North/	South Line	Feet from the	East/West Lir	e County	7	
'M'	34	19-5	38-E						LEA		
			Latitu	de <u>N32°41`54.</u> 4	40"	Longitude	W103° <b>08</b> `34.	90"			
				_		OF REL	_				
Type of Rele	ase				UKE	Volume of		Volun	e Recovered	d	
Crude oil and		water				<1 bbls			<1 bbls		
Source of Release									Date and Hour of Discovery		
3" flow line Was Immediate Notice Given?						02/16/2007 09:45 AM 02/16/2 If YES, To Whom?			007 09:45 AM		
Was Immediate Notice Given?						I N/A			02122-22425		
By Whom? N/A						02/10/2007/09.45/AM 02/10/2007/09.45/AM   If YES, To Whom? 02/10/2007/09.45/AM   N/A 02/10/2007/09.45/AM   Date and Hour N/A 02/10/2007/09.45/AM				2	
Was a Watercourse Reached?						If YES, Volume Impacting the WaterCourse.					
🗌 Yes 🛛 No						N/A	· · · ·		1613		18
If a Watercou	urse was Im	pacted, Descri	be Fully.	k					Receiv Hobbs	<del>'00</del>	-81
			2						OCD		¥/
Describe Are Spilled flui fluid was re truck on the be excavated information	a Affected d ran alon covered vi corner of d and repa only, due	and Cleanup A g curb for ab ia vacuum tru Leech and D ired. Due to to public rep	Action Tal out a city uck. A tr unnam. minimal ort of sp	block, north to ansport truck lo All rinse water fluid loss and d	the cor aded wi and spil lamage,	ner of Leecl ith fresh wa lled fluid wa no further y	n and Dunnam. ter was called an is recovered and work is planned	There is no ci nd entire area I hauled to an at this site. T	was over fl approved d his report b	ushed to lisposal. being sen	vacuum Piping will t, for
regulations al public health should their c or the enviror	Il operators or the envir operations h nment. In a	are required to ronment. The lave failed to a	o report ar acceptanc dequately CD accep	nd/or file certain r ee of a C-141 repo investigate and r tance of a C-141	elease no ort by the emediate	otifications and NMOCD m e contaminati	nd perform correct arked as "Final R on that pose a thr e the operator of	tive actions for eport" does not eat to ground w responsibility fo	releases white relieve the content of the content ater, surface r compliance	ich may e operator o water, hu e with an	ndanger f liability uman health
Signature STEVEN MIBISHED						OIL CONSERVATION DIVISION					
Printed Name	e: Steven M	. Bishop		0	1	Approved by	District Supervis	or A	le-		
Title: HES Te	echnician					Approval Dat	e: 3,14.07	K Expirati	on Date: -		
E-mail Addre	ess: Steven	Bishop@oxy.	com	maa A	TRA (	Conditions of	Approval:		Attach	ned 🗌	
Date: 02/15		Shoota If NI-	Pho	<b>3 90 4</b> ne: (505) <b>3</b> 97-825	51		<b>C</b>				
		Sheets If Ne ACO708	0252	817	appl	lication	pPACO;	1080.259	29	Rf	0#125