

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Mickey Garner
Address	3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No.	505.391.3158
Facility Name	VGEU West Battery	Facility Type	Oil and Gas

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No
---------------	---------------------	---------------	---------------------	----------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	31	17S	35E					Lea

Latitude 32.79744 N Longitude 103.48840 W

#### NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Crude Oil	10bbl (10oil, 0water)	(9oil, 0water)
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Skimmed Oil Tank	03-17-2007 10:00 pm	03-17-2007 10:45 pm
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	N/A	
By Whom?	Date and Hour	
N/A	N/A	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*

The spill resulted from the Skimmed Oil Tank overflowing due to an automatic valve malfunction. The MSO shut in the lease and called a vacuum truck to pick up free liquids.

Describe Area Affected and Cleanup Action Taken.\*

A 20'X 50' area of caliche pad was affected. No cattle in the area. The spill site will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Mickey Garner	Approved by District Supervisor:	
Title: HSER Lead	Approval Date: 3-21-07	Expiration Date: 6-21-07
E-mail Address: Mickey.D.Garner@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03-21-2007 Phone: 505.391.3158	Final C-141 report completed	

• Attach Additional Sheets If Necessary

Facility: APAC0708127451  
Incident: APAC0708127518  
Application: APAC070812760

(RP# 1261