

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company CHEVRON MIDCONTINENT L.P.	Contact Danny Lovell
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1242 (office), 505-390-0866 (cell)
Facility Name- H.T. MATTERN "D"	Facility Type - PRODUCTION

Surface Owner- SAM BRUTON	Mineral Owner - State of New Mexico	Lease No.
---------------------------	-------------------------------------	-----------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	1	22S	37E					Lea

Latitude-32-25' Longitude 103-12'

NATURE OF RELEASE

Type of Release-Produced Water and Oil	Volume of Release 4 BO, 16 BW	Volume Recovered- 3 3/4BO & 15 BW
Source of Release- WATER TANK	Date and Hour of Occurrence- 5/1/07 @ ?	Date and Hour of Discovery 5/1/07 @ 13:00 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Bill Anderson	Date and Hour 5/2/07 @ 09:51	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
WATER TRANSFER PUMP KICKED OUT ON OVERLOAD. RESET PANEL AND PUMP TANK DOWN. INSTALLED HIGH LEVEL SHUTDOWN ON WELL#11.

Describe Area Affected and Cleanup Action Taken.* MAJORITY OF FLUID CONTAINED WITHIN BERMED AREA OF TANK. APPROXIMATELY 1 BBLS RAN IN PASTURE DOWN COW TRAIL 300' X 2'. FLUID IN BERMED AREA WAS VACCUMED UP. DGW=75'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Danny Lovell</i>	OIL CONSERVATION DIVISION	
Printed Name: Danny Lovell	Approved by District Supervisor: <i>[Signature]</i>	
Title: Operations Supervisor	Approval Date: 5-11-07	Expiration Date: 7-11-07
E-mail Address: lovda@chevron.com	Conditions of Approval:	
Date: 5/2/07 Phone: 505-394-1242	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Facility - PPACO713428577
incident - n PPACO713428652
application - p PPACO713428787

RP# 1317