

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Southern Union Gas Services, Ltd.	Contact	Tony Savoie
Address	P.O. Box 1226 Jal, N.M. 88252	Telephone No.	505-395-2116
Facility Name	Lea County Field Dept.	Facility Type	Natural Gas Gathering

Surface Owner: Federal	Mineral Owner: Federal	Lease No.
------------------------	------------------------	-----------


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	26	25S	37E					Lea

Latitude N32 5.775 Longitude W103 7.925

**NATURE OF RELEASE**

Type of Release : Crude Oil and Natural Gas	Volume of Release: 70 Bbls Crude Oil and 80MCF Nat. Gas	Volume Recovered 60 Bbls crude Oil
Source of Release : 410 Bbl. Storage Tank	Date and Hour of Occurrence 4/23/07 Time 10:45 a.m.	Date and Hour of Discovery 4/23/07 Time: 10:45 a.m..
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Tony Savoie	Date and Hour: 4/23/07 12:55 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A Construction company ditching a new Right of Way hit a 6" natural gas pipeline with a ditching machine. The line was immediately shut down and isolated and the ditch line was blocked off within 50 ft. of the damaged line. A vacuum truck was dispatched to the site and approximately 60 bbls of crude oil was recovered from the ditch line. All of the impacted soil was excavated and placed on plastic the same day. Samples were collected from the bottom of the ditch to assure all of the impacted soil was brought to the surface.

Describe Area Affected and Cleanup Action Taken. The impacted area was contained to the ditch line measuring approximately 50 ft. long by 4 ft. wide. All of the impacted soil was removed from the ditch line and placed on plastic pending remediation or transfer to SUGS landfarm. The final remediation will follow the NMOCD guidelines for the remediation of leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: John A. Savoie		Approved by District Supervisor: <i>[Signature]</i>	
Title: Remediation Supervisor		Approval Date: 5-11-07	Expiration Date: 9-11-07
E-mail Address: tony.savoie@sug.com		Conditions of Approval:	
Date: 5/8/07 Phone: 505-395-2116		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

incident - NPAC0713431284  
application - NPAC0713431448

DESTRUCTION SAMPLES &  
DOCUMENTATION OF CLOSURE R# 309