| <u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | | | State of New Mexico Energy Minerals and Natural Resource Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 | | | vision tis Dr. 505 | NA Re | Y 2007 Ceived Hobbs | Sommit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form | | | |
|--|--|---|--|--|--------------------------------|---|---|-------------------------------------|--|--|--------------------------------------|-------------------------------|--|
| | | | Rele | ease Notific | eatio | | orrective | Acti | on | 100 | | | |
| | | | | | | | ATOR | <u>76597</u> | 11 18 24 22 | itial Report | x F | inal Report | |
| Name of Company Chesapeake Energy Address 1616 west Bender BLVD | | | | | | Contact Bradley Blevins Telephone No. 505-441-0341 | | | | | | | |
| Facility Name Bobbi #5 Battery | | | | | | Facility Type Production | | | | | | | |
| Surface Owner Mineral | | | | | | er Lease No.API 3002527641 | | | | | | | |
| | | | | | | ON OF RE | FASE | | | | | | |
| Unit Letter | Section | Township | Range | Feet from the | | h/South Line | Feet from t | he Ea | st/West Line | County | | | |
| | 20 | 18s | 36e | | | Lea | | | | Lea | | | |
| L | L | L | I a | titude | | Longitud | | , <u> </u> | | | | | |
| NATURE OF RELEASE | | | | | | | | | | | | | |
| Type of Rele | | | | | | | | | | | | | |
| Source of Release tank struck by lightning | | | | | | | and Hour of Occurrence Date and Hour of Discovery | | | | - | :15am | |
| Was Immedi | ata Nation (| Timen? | ··· | | | 6:00am | | 107 | | | | | |
| was inineur | | | Gary Wi | ink | | | | | | | | | |
| x Yes No Not Required By Whom? Bradley Blevins | | | | | | Date and Hour 5-8-07 9:00am | | | | | | | |
| Was a Watercourse Reached? | | | | | | If YES, Volume Impacting the Watercourse. | | | | | | | |
| If a Watercourse was Impacted, Describe Fully.* | | | | | | | | | | | | | |
| Describe Cause of Problem and Remedial Action Taken.* Tank battery was struck by lightning, blowing top off tank and causing tank to catch fire, fluid was contained inside steel tank. Hobbs fire dept responded and put fire out. | | | | | | | | | | | | | |
| Describe Area Affected and Cleanup Action Taken.* Hobbs fire dept sprayed tank with foam, no production fluid was on ground. | | | | | | | | | | | | | |
| regulations a public health should their or the enviro | Il operators or the envi operations h nment. In a | are required to ronment. The have failed to | to report and acceptane adequately OCD accept | e is true and comp nd/or file certain r ce of a C-141 repo v investigate and r otance of a C-141 | release ort by t remedia | notifications a the NMOCD m ate contaminat | nd perform c harked as "Fir ion that pose | orrective al Repor a threat t | actions for re rt" does not rel to ground wate | leases which lieve the oper er, surface wa | may end rator of li ater, huma | anger ability an health | |
| | | | | | | OIL CONSERVATION DIVISION | | | | | | | |
| Signature: Tradley Delerino | | | | | | - | | | | | | | |
| Printed Name: Bradley Blevins | | | | | | Approved by District Supervisor: | | | | | | | |
| Title: Enviro | Title: Environmental Field Tech | | | | | | pproval Date: Expiration Date: | | | | | | |
| E-mail Address:bblevins@chkenergy.com | | | | | | Conditions of Approval: | | | | Attached | | | |
| Date: 5-8-0 | Phone:505-441-0 | | | | | | | | | | | | |
| Thursday Thu agg | dent licat | - nP | ACO PAC | Phone:505-441-0 134520 0713452 | 185 | ŚŚ | | | | RP4 | ±13 | 25 | |







