

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company - J Cleo Thompson	Contact - Jim Stevens
Address - P O Box 12577 Odessa, TX 79768	Telephone No. - 432-550-8887
Facility Name - Milnesand Unit #519	Facility Type - Flowline

Surface Owner - Private	Mineral Owner	Lease No. 30.041.10160
-------------------------	---------------	------------------------

LOCATION OF RELEASE

Unit Letter I	Section 25	Township 8S	Range 34E	Feet from the 1980	North/South Line FSL	Feet from the 660	East/West Line FEL	County Roosevelt
------------------	---------------	----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	---------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE



Type of Release - Oil	Volume of Release - Unknown	Volume Recovered - None
Source of Release - Flowline	Date and Hour of Occurrence ?	Date and Hour of Discovery 4-23-07 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Hobbs OCD	
By Whom? John Hughes - Foreman	Date and Hour 4-23-07 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\* Flowline leaked at the pad of the Milnesand Unit #203 next to the abandoned well marker. MSU #203 is located at UL 'H' Sec.25 T8S R34E. Elke Environmental was called to look at spill and will have equipment on site to remediate the spill within a week. **GW is greater than 100'**

Describe Area Affected and Cleanup Action Taken.\* Area affected is 60' x 90' surface oil stain. Area is NOT used for cattle. Elke Environmental will delineate the spill and remediate according to NMOCD guidelines. A closure report will be submitted at the end of the job.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Logan Anderson	Approved by District Supervisor: 	
Title: Consultant	Approval Date: 5.16.07	Expiration Date: 7.16.07
E-mail Address: la_elkeenv@yahoo.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-24-07	Phone: 432-366-0043	

\* Attach Additional Sheets If Necessary

Incident - n PAC0714248257  
application - pPAC0714248310

1RP. 1340