District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

						OPERA	TOR		X Initi	al Report L	_ Final R	eport	
Name of Co	mpany La	tigo Petrolei	ım, Inc.			Contact Lisa Hunt							
Address P			9702-7340		Telephone No. (432)685-8229								
Facility Nar]	Facility Type Tank Battery							
Careford Or	man Stata -	f NIM	Mineral O	NI CONTRACTOR	NM Lagga No								
Surface Ow	ner State 0	OI INIVI											
		, . · ·		,		OF RE				·			
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/V	West Line	County			
В	2	18S	33E							Lea			
··	(4	I.a	titude	•	Longitude							
NATURE OF RELEASE													
Type of Release Spill Volume of Release 50 BO/30 BW Volume Recovered Still recovering													
Source of Re		Battery			Date and Hour of Occurrence 5/10/07 Date and Hour of Discovery 5/11-1:00p								
Was Immedia			No Not Re	quired	If YES, To Whom? @ 11pm								
By Whom?]	Lisa Hunt				Date and Hour 5/11/07 - 3:00 pm								
Was a Water					If YES, Volume Impacting the Watercourse.								
] No										
If a Watercourse was Impacted, Describe Fully.*													
15 to 17 18 19 19 19 19 19 19 19 19 19 19 19 19 19													
A The state of the													
Describe Cause of Problem and Remedial Action Taken.*												, I	
Describe Cause of Problem and Remedial Action Taken.* Oil and water dump plug failure. Received Hobbs													
은 Received 등 Hobbs 유												ภู่ ว	
Decembe A	a Affanta I	and Claanur	Action Tal	ran *						Hobbs OCD	s (5)	"/	
Describe Area Affected and Cleanup Action Taken.* Due to recent heavy rains the ground is very saturated so the spill just ran and didn't soak in. Currently, there is work being done to													
Due to recent heavy rains the ground is very saturated so the spill just ran and didn't soak in. Currently, there is work being done to recover the spill. Once the area is cleaned up and remediated we will send another updated C-141.													
	· CI TEOS												
I hereby certi	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
				nd/or file certain re								1	
public health	or the envi	ronment. The	acceptano	ce of a C-141 repo	rt by the	NMOCD m	arked as "Final Re	eport" d	loes not rel	ieve the operator	of liability		
				investigate and re								.h	
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
		1			OIL CONSERVATION DIVISION								
Signature:	Lin) L.											
	- 1 24	· 10			Approved by District Supervisor:								
Printed Name:Lisa Hunt						Approved by District Supervisor.							
Title: Regu	latory Ana	alyst			Approval Date: 5-22-87 Expirat				on Date: 7-22.07				
					Approved Dates G. Office (
E-mail Addre	ess:huntl@	pogoproduc		(Conditions of Approval:				Attached				
Date: 05/11/	2007		(432)685-8229		SUBMIT FRANC C-141 W								
Attach Addit	tional Shee	ets If Necess							1 ,				
D 1	IA-F	PHC07	8634		SUPERTING TAMPLE DATA FOR CLOSURE.						0		
gall	wy-,	$\bigcap \bigcap \bigcap \bigcap \bigcap$	218710		106 0	warle.			KP1	-134			
Char. La	2018-1	n PHO	114	12100	$\overline{}$								
Attach Additional Sheets If Necessary, 248634 FOR CLOSURE. PACO7 14248634 FOR CLOSURE. PACO7 14248797 CAPPLICATE - PACO7 14248797													
yzilli	Catio	~r'''	/1		*								