

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ExxonMobil	Contact Toni Collier
Address P.O. Box 4358, Houston, TX 77210	Telephone No. 281-654-1133
Facility Name BDT State S	Facility Type Drain line

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No.
-----------------------------------	-----------------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section 2	Township 22S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude N32.25.26 Longitude W103.08.122

NATURE OF RELEASE

Type of Release Oil and water	Volume of Release 5.1bbls oil/5.1 bbls water	Volume Recovered 3 bbls oil/0 bbls water
Source of Release drain line	Date and Hour of Occurrence 5/1/07 8:00AM	Date and Hour of Discovery 5/1/07 8:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Shelby Pennington	Date and Hour 5/1/07 2:30PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

2" drain line on production separator broke due to corrosion.

Describe Area Affected and Cleanup Action Taken.*

Free fluid picked up. Drain line has been repaired. Remediation plan will be submitted.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>Timothy O. Cagle</i>	OIL CONSERVATION DIVISION	
Printed Name: Timothy O. Cagle	Approved by District Supervisor <i>[Signature]</i>	
Title: Compliance Supervisor	Approval Date: 5.18.07	Expiration Date: 7.18.07
E-mail Address: timothy.o.cagle@exxonmobil.com	Conditions of Approval: ① NEED AERIAL DIMENSIONS OF SPILL Attached <input type="checkbox"/> ② NEED CHLORIDES OF WATER SPILLED	
Date: 5/9/07 Phone: 281-654-1001		

* Attach Additional Sheets If Necessary

Facility - PAC0714248943
Incident - PAC0714249298

application - PAC0714249452
RPT# 1346