

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Mickey D. Garner
Address	3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No.	505.391.3158
Facility Name	EVGSAU 1911-002	Facility Type	Oil and Gas

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No	30-025-26857-00-00
---------------	---------------------	---------------	---------------------	----------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	19	17S	35E					Lea

Latitude N 32.81392 Longitude W 103.49675

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 33bbl (0oil, 33water)	Volume Recovered (0oil, 15water)
Source of Release Wellhead surface casing	Date and Hour of Occurrence 6/5/2007 10:00	Date and Hour of Discovery 6/5/2007 12:20
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Mickey Garner	Date and Hour 6/5/2007 16:20	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

The leak resulted from a downhole tubing or packer failure and communication to the surface casing. The MSO shut in the well and called a vacuum truck to pick up free liquids. No cattle were in the area.

Describe Area Affected and Cleanup Action Taken.*

A 130' X 100' of prepared location pad and roadway. The location will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Mickey D. Garner	Approved by District Supervisor: 	
Title: HSER Lead	Approval Date: 6.11.07	Expiration Date: 8.11.07
E-mail Address: Mickey.D.Garner@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/6/2007 Phone: 505.391.3158	SUBMITAL OF FINAL C-141	

- Attach Additional Sheets If Necessary

W/ SUPPORTING DOCUMENTATION BY

RP# 1407