

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>Mickey Garner</b>
Address <b>3300 North A St. Bldg 6, Midland, TX 79705-5406</b>	Telephone No. <b>505.391.3158</b>
Facility Name <b>VEGU West Battery</b>	Facility Type <b>Oil and Gas</b>

Surface Owner <b>State of New Mexico</b>	Mineral Owner <b>State of New Mexico</b>	Lease No
--	--	----------

**LOCATION OF RELEASE**

Unit Letter <b>A</b>	Section <b>31</b>	Township <b>17S</b>	Range <b>35E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude **32.79744 N** Longitude **103.48840 W**

**NATURE OF RELEASE**

Type of Release <b>Crude Oil</b>	Volume of Release <b>10bbl (10oil, 0water)</b>	Volume Recovered <b>(9oil, 0water)</b>
Source of Release <b>Skimmed Oil Tank</b>	Date and Hour of Occurrence <b>03-17-2007 10:00 pm</b>	Date and Hour of Discovery <b>03-17-2007 10:45 pm</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>N/A</b>	
By Whom? <b>N/A</b>	Date and Hour <b>N/A</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*  
**N/A**

Describe Cause of Problem and Remedial Action Taken.\*

**The spill resulted from the Skimmed Oil Tank overflowing due to an automatic valve malfunction. The MSO shut in the lease and called a vacuum truck to pick up free liquids.**

Describe Area Affected and Cleanup Action Taken.\*

**A 20'X 50' area of caliche pad was affected. No cattle in the area. The spill site was delineated and remediated in accordance with NMOCD guidelines. Impacted soil totaling 426 cubic yards was excavated and disposed of at Sundance's facility. Confirmation samples were taken and are attached. Chris Williams approved closure and the site was backfilled.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Mickey Garner</b>		Approved by District Supervisor: <i>Chris Williams</i>	
Title: <b>HSER Lead</b>		Approval Date: <b>6/27/07</b>	Expiration Date: <b>6/27/07</b>
E-mail Address: <b>Mickey.D.Garner@conocophillips.com</b>		Conditions of Approval:	
Date: <b>03-21-2007</b> Phone: <b>505.391.3158</b>		Attached <input type="checkbox"/>	

- Attach Additional Sheets If Necessary

R.P.# 1261



PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR  
BBC INTERNATIONAL, INC.  
ATTN: CLIFF BRUNSON  
P.O. BOX 805  
HOBBS, NM 88241  
FAX TO: (505) 397-0397


Receiving Date: 04/18/07  
Reporting Date: 04/19/07  
Project Owner: CONOCO PHILLIPS  
Project Name: VACUUM GLORIETTA WEST T.B.  
Project Location: BUCKEYE, NM

Sampling Date: 04/17/07  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: BC  
Analyzed By: BC/HM

LAB NUMBER	SAMPLE ID	GRO	DRO	CI*
		(C <sub>6</sub> -C <sub>10</sub> ) (mg/Kg)	(>C <sub>10</sub> -C <sub>28</sub> ) (mg/Kg)	(mg/Kg)
ANALYSIS DATE		04/18/07	04/18/07	04/18/07
H12477-1	SP1 @ 5'	<10.0	<10.0	240
H12477-2	SP2 @ 3'	<10.0	<10.0	280
H12477-3	BKGND @ 0-6"	<10.0	<10.0	<16
Quality Control		780	791	490
True Value QC		800	800	500
% Recovery		97.5	98.9	98.0
Relative Percent Difference		4.4	0.6	2.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; CI: Std. Methods 4500-CI'B

\*Analyses performed on 1:4 w:v aqueous extracts.

  
Chemist

4/18/07  
Date

H12477A BBC

PLEASE NOTE: **Liability and Damages** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analysis. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240


ANALYTICAL RESULTS FOR  
BBC INTERNATIONAL, INC.  
ATTN: CLIFF BRUNSON  
P.O. BOX 805  
HOBBS, NM 88241  
FAX TO: (505) 397-0397

Receiving Date: 04/18/07  
Reporting Date: 04/19/07  
Project Owner: CONOCO PHILLIPS  
Project Name: VACUUM GLORIETTA WEST T.B.  
Project Location: BUCKEYE, NM

Sampling Date: 04/17/07  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: BC  
Analyzed By: BC

LAB NUMBER	SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DATE		04/18/07	04/18/07	04/18/07	04/18/07
H12477-1	SP1 @ 5'	<0.005	<0.005	<0.005	<0.015
H12477-2	SP2 @ 3'	<0.005	<0.005	<0.005	<0.015
H12477-3	BKGND @ 0-6"	<0.005	<0.005	<0.005	<0.015
Quality Control		0.100	0.100	0.095	0.273
True Value QC		0.100	0.100	0.100	0.300
% Recovery		100	100	94.8	90.9
Relative Percent Difference		0.3	1.4	4.7	3.3

METHOD: EPA SW-846 8260

  
Chemist

4/19/07  
Date

PLEASE NOTE: **Liability and Damages** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analysis. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240  
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

## Page 1 of 1

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.