


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form



Release Notification and Corrective Action

OPERATOR

Name of Company <u>Latigo Petroleum, Inc.</u>	Contact <u>Lisa Hunt</u>
Address <u>P.O. Box 10340 Midland, TX 79702-7340</u>	Telephone No. <u>(432)685-8229</u>
Facility Name <u>Central Corbin Queen Unit</u>	Facility Type <u>Tank Battery</u>
Surface Owner <u>State of New Mexico</u>	Mineral Owner <u>NM</u>
Lease No. _____	

LOCATION OF RELEASE

Unit Letter <u>K</u>	Section <u>4</u>	Township <u>18S</u>	Range <u>33E</u>	Feet from the _____	North/South Line _____	Feet from the _____	East/West Line _____	County <u>Lea</u>
-------------------------	---------------------	------------------------	---------------------	------------------------	---------------------------	------------------------	-------------------------	----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>Oil spill</u>	Volume of Release <u>35 BO</u>	Volume Recovered <u>None</u>
Source of Release <u>Tank battery</u>	Date and Hour of Occurrence <u>6/20/07</u>	Date and Hour of Discovery <u>2/20/07</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Gary Wink</u>	
By Whom? <u>Bill Hearne</u>	Date and Hour <u>2/20/07 @ 3:45 pm</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

WTR < 50'

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Tank spill ran over. Most was contained in the firewall. There was an area 60 x 20' affected outside the firewall. Backhoe is working to clean up.

Describe Area Affected and Cleanup Action Taken.*

Highlander has been notified and should be out soon to remediate soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <u>Lisa Hunt</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Lisa Hunt</u>	Approved by District Supervisor: <u>[Signature]</u>	
Title: <u>Regulatory Analyst</u>	Approval Date: <u>6-27-07</u>	Expiration Date: <u>8-27-07</u>
E-mail Address: <u>huntl@pogoproducing.com</u>	Conditions of Approval: <u>Final DCE BY</u>	
Date: <u>06/21/2007</u> Phone: <u>(432)685-8229</u>	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

#500
RPH 1441