

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company ChevronTexaco	Contact Wayne Minchew
Address HCR 60 Box 423 Lovington, N.M. 88260	Telephone No. 505-396-4414
Facility Name Central Vacuum Unit #114	Facility Type Injection well

Surface Owner State of NM	Mineral Owner State of NM	Lease No. 857943
---------------------------	---------------------------	------------------

LOCATION OF RELEASE

30025257990000

Unit Letter K	Section 6	Township 18S	Range 35E	Feet from the 1460	South Line	Feet from the 2100	West Line	County Lea
------------------	--------------	-----------------	--------------	-----------------------	------------	-----------------------	-----------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 250 Bbls.	Volume Recovered 200 Bbls.
Source of Release Tubing flange	Date and Hour of Occurrence 7/29/2006 09:00 AM	Date and Hour of Discovery 7/29/2006 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Wayne Minchew	Date and Hour 7/29/2006 2:30 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Internal corrosion destroyed threads on flange allowing tubing valve to blow off. Flowed well down and replaced valve. Vacuum truck recovered 200 barrels water

Describe Area Affected and Cleanup Action Taken.\*

30' x 200' of pasture - vacuum truck picked up loose water - contaminated soil will be removed

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>P. W. Minchew</u>	OIL CONSERVATION DIVISION	
Printed Name: P. W. Minchew	Approved by District Supervisor: <u>Enrique Lopez</u>	
Title: Operations Supervisor	Approval Date: <u>6-26-07</u>	Expiration Date: <u>9-26-07</u>
E-mail Address: pminchew@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/31/2006 Phone: 396-4414	<u>SUBMITTAL OF FINAL C-141</u>	

\* Attach Additional Sheets If Necessary

RPH 1448