

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Mickey Garner
Address 4001 Penbrook, Odessa, TX 79762-5917	Telephone No. 505.391.3158
Facility Name EVGASU WELL # 3308-007	Facility Type Oil and Gas

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No API # 30-025-32219
--	--	------------------------------------

LOCATION OF RELEASE

Unit Letter E	Section 33	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude **32.79347N** Longitude **-103.47073W**

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water W/Chlorides = 58,000mg/L	Volume of Release 18.2 bbl (2 oil, 16.2 water)	Volume Recovered (2 oil, 12 water)
Source of Release 2 7/8" Flowline	Date and Hour of Occurrence 10/05/2006 0900hrs	Date and Hour of Discovery 10/05/2006 1515hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The cause of the spill was a flow line leak due to internal corrosion. The failed section of flow line will be replaced.		
Describe Area Affected and Cleanup Action Taken.* 18'X126' of dry black soil/caliche rock pasture with no cows present. The spill site will be delineated and remediated in accordance with NMOCD guidelines. Impacted soil totaling 504 cubic yards was excavated and disposed of at Sundance's facility. Confirmation samples were taken and are attached. Chris Williams approved closure and the site was backfilled.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:		OIL CONSERVATION DIVISION
Printed Name: Mickey Garner	Approved by District Supervisor: <i>Chris Williams</i>	
Title: HSE Lead	Approval Date: <i>7/5/07</i>	Expiration Date: <i>7/5/07</i>
E-mail Address: Mickey.D.Garner@conocophillips.com	Conditions of Approval:	
Date: 10/09/2006 Phone: 505.391.3158	Attached <input type="checkbox"/>	

• Attach Additional Sheets If Necessary

RP# 1084



PHONE (505) 393-2326 • 101 E MARLAND • HOBBS, NM 88240

Receiving Date: 06/25/07
Reporting Date: 06/25/07
Project Owner: CONOCO PHILLIPS
Project Name: EVGSAU 3308-007
Project Location: BUCKEYE, NM

Analysis Date: 06/25/07
Sampling Date: 06/21/07
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: HM
Analyzed By: HM

LAB NO.	SAMPLE ID	Cl ⁻ (mg/Kg)
H12799-1	007 SP1	144
H12799-2	007 SP2	128
Quality Control		490
True Value QC		500
% Recovery		98
Relative Percent Difference		1.0

4500-CI-B


Note: Analyses performed on 1:4 w:v aqueous extracts.

Chemist

Date _____

H12799 BBC

PLEASE NOTE **Liability and Damages** **Cardinal's** liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by **Cardinal** within thirty (30) days after completion of the applicable service. In no event shall **Cardinal** be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by **Cardinal**, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240

(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

Page 1 of 1[illegible]

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.