

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Mickey D. Garner
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU 3333-001	Facility Type Oil and Gas

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No API#30-025-02981-00-00
--	--	--

LOCATION OF RELEASE

Unit Letter H	Section 33	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude **32.79316 N** Longitude **103.45582 W**

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 23.3bbl (5.3oil, 18water)	Volume Recovered (5oil, 15water)
Source of Release Stuffing Box	Date and Hour of Occurrence 02-17-2007 3:00 am	Date and Hour of Discovery 02-17-2007 7:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Brad Boroughs	Date and Hour 02-17-2007 7:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Backpressure valve plugged resulting in stuffing box rubber failure. MSO shut in well and called vacuum truck to pick up free liquids.

Describe Area Affected and Cleanup Action Taken.*

An area of Pad and Pasture 28' X 127' was affected. No cows were present. The spill site will be delineated and remediated in accordance with NMOCD guidelines. Impacted soil totaling 552 cubic yards was excavated and disposed of at Sundance's facility. Confirmation samples were taken and are attached. Chris Williams approved closure and the site was backfilled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Mickey D. Garner	Approved by District Supervisor: <i>Chris Williams</i>	
Title: HSER Lead	Approval Date: <i>7/5/07</i>	Expiration Date: <i>7/5/07</i>
E-mail Address: Mickey.D.Garner@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06-27-07 Phone: 505.391.3158		

- Attach Additional Sheets If Necessary

RP#1252



ARDINAL LABORATORIES

PHONE (325) 873-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
BBC INTERNATIONAL, INC.
ATTN: CLIFF BRUNSON
P.O. BOX 805
HOBBS, NM 88241
FAX TO: (505) 397-0397

Receiving Date: 06/25/07
Reporting Date: 06/27/07
Project Owner: CONOCO PHILLIPS
Project Name: EVGSAU 3333-001
Project Location: BUCKEYE, NM

Sampling Date: 06/21/07
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: HM
Analyzed By: LB/HM

LAB NUMBER	SAMPLE ID	GRO (C ₈ -C ₁₂) (mg/Kg)	DRO (C ₁₂ -C ₂₈) (mg/Kg)	Cl [*] (mg/Kg)
		06/26/07	06/26/07	06/25/07
H12801-1	001 SP1	<25.0	<25.0	16
H12801-2	001 SP2	<25.0	<25.0	16
H12801-3	001 SP3	<25.0	<25.0	480
H12801-4	001 SP4	<25.0	120	288
Quality Control		754	909	490
True Value QC		1000	1000	500
% Recovery		75.4	90.9	98.0
Relative Percent Difference		0.8	6.8	1.0

To 6W
OK - CUB

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl^{*}: Std. Methods 4500-Cl^{*}B

*Analyses performed on 1:4 w:v aqueous extracts.


Chemist

6/27/07
Date

H12801A BBC

PLEASE NOTE: **Liability and Damages.** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages including, without limitation, business interruptions, loss of use or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



ARDINAL LABORATORIES

PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
BBC INTERNATIONAL, INC.
ATTN: CLIFF BRUNSON
P.O. BOX 805
HOBBS, NM 88241
FAX TO: (505) 397-0397

Receiving Date: 06/25/07
Reporting Date: 06/26/07
Project Owner: CONOCO PHILLIPS
Project Name: EVGSAU 3333-001
Project Location: BUCKEYE, NM

Sampling Date: 06/21/07
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: HM
Analyzed By: AB


LAB NUMBER	SAMPLE ID	BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)
ANALYSIS DATE		06/25/07	06/25/07	06/25/07	06/25/07
H12801-1	001 SP1	<0.002	<0.002	<0.002	<0.006
H12801-2	001 SP2	<0.002	<0.002	<0.002	<0.006
H12801-3	001 SP3	<0.002	<0.002	<0.002	<0.006
H12801-4	001 SP4	<0.002	<0.002	<0.002	<0.006
Quality Control		0.115	0.102	0.102	0.316
True Value QC		0.100	0.100	0.100	0.300
% Recovery		115	102	102	105
Relative Percent Difference		3.1	2.0	5.5	7.4

METHOD: EPA SW-846 8021B


Chemist

6/26/07
Date

PLEASE NOTE: **Liability and Damages** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for an analysis. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



{915} 673-7001 Fax {915} 673-7020 (505) 393-2326 Fax (505) 393-2476

Page (of)

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.