

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Jesse A. Sosa
Address	3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No.	(505)391-3126
Facility Name	Warren Unit Water Transfer Line	Facility Type	Produced water trunk line
Surface Owner	Bob McCasland	Mineral Owner	BLM
		Lease No.	LC031695B

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	28	20S	38E					Lea

Latitude N 32 32.512 Longitude W 103 09.256

NATURE OF RELEASE

WTR ≈ 50'

Type of Release	Produced water	Volume of Release	22	Volume Recovered	15
Source of Release	Victaulic nipple in trunk line	Date and Hour of Occurrence	6/20/07 4:00 pm	Date and Hour of Discovery	6/20/07 5p
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Pat Richards (voicemail)		
By Whom?	Jesse Sosa	Date and Hour	6/22/2007 2:35 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



There was an accidental discharge of 22 BPW from a victaulic nipple on transfer line header. The nipple was on a 3" polyline upstream of header. The spill was not contained in a dike and 15 BPW fluid was recovered.

NEED CHLORIDES OF WTR SPILLED

Describe Area Affected and Cleanup Action Taken.*

Affected area was 15' X 120' all on pasture land. MSO called a vacuum truck out and 15 bbls was recovered. No cows were presence. Area will be remediated in accordance with NMOCD guidelines. Regulatory Agencies were notified.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa		Approved by District Supervisor: 	
Title: HSER Lead		Approval Date: 7.18.07	Expiration Date: 9.18.07
E-mail Address: Jesse.A.Sosa@conocophillips.com		Conditions of Approval:	
Date: 06/29/2007 Phone: (505)391-3126		Submitted FINAL C-141 B-4	

* Attach Additional Sheets If Necessary

ATTACH DOCUMENTATION OF CLEANUP
PROVIDE SPILL CHLORIDES

RP#1493