

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company EOTT Energy Pipeline	Contact Frank Hernandez
Address 5805 East Highway 80 / P.O. Box 1660, Midland, TX 79703	Telephone No. 915.638.3799
Facility Name Scharb to Vacuum 4" Gathering	Facility Type 4" Crude Oil Pipeline

Surface Owner State of New Mexico	Mineral Owner	Lease No.
--------------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter N	Section 33	Township 18S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County: Lea Lat.: 32° 41' 54.45"N Long.: 103° 27' 52.94"W
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 20 bbls	Volume Recovered 5 bbls
Source of Release 4" Steel Pipeline	Date and Hour of Occurrence 4-23-02 1400 hours	Date and Hour of Discovery 4-23-02 1400 hours
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Paul Sheeley	
By Whom? Frank Hernandez	Date and Hour 4-23-02 1600 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*
External corrosion. Line replaced and contaminated soil placed on plastic barrier on site.

Describe Area Affected and Cleanup Action Taken.*
Area = ~9,777 ft². (245' x 75') Liquids vacuumed and reintroduced into system. Contaminated soil excavated and placed on plastic barrier. Site to be delineated and remediation plan developed and submitted to the NMOCD for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Frank Hernandez</i>	OIL CONSERVATION DIVISION	
Printed Name: Frank Hernandez	Approved by District Supervisor: <i>[Signature]</i>	
Title: District Environmental Supervisor	Approval Date: 8-28-07	Expiration Date: _____
Date: April 28, 2002 Phone: 915.638.3799	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary



RP# 1534