<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St. Francis Dr. Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Form C-141

Revised October 10, 2003

side of form

Release Notification and Corrective Action

						0	PERATOR		X	Initial Report	Final Report	
		tes Petroleum				e Stubblefield						
Address 105 South 4th Street, Artesia, N.M. 88210						Telephone No 505-7484500 505-513-1712						
Facility Name Lotus "ALT" tank battery						Facility Type Tank Battery						
Surface Owner Federal Mineral Owner									Lease	No. 34562		
											9,	
,					N OF REI			<u>/6</u>	A 30.	°02/		
Unit Letter G						th/South Line Feet from the Ea 1980 FE			est Linge	Lea 2007	121314	
Tacility Name Lotus "ALT" tank battery Facility Type Tank Battery												
		NA'	OF REL	EASE		/1	کر _{کر}	SIL				
Type of Relea	ise. Produce	ed water			Volume of Release >330 bbls Produced water			Volume Recovered 120000 330 bbls produced water				
Source of Release High pressure discharge line at pump							Date and Hour of Occurrence 10/19/2007 4:00pm			Date and Hour of Discovery 10/19/2007 4:00pm		
Was Immediate Notice Given? X Yes No Not Required						If YES. To Whom? Jerry Fanning left release report on after hour's office voice mail box						
By Whom? Jerry Fammig, Jr.						Date and Hom 10/20/2007 12.40pm						
Was a Watercourse Reached? Yes X No						If YES. Volume Impacting the Watercourse						
If a Watercou	rse was Imp	acted. Describ	e Fully.*							4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4		
Describe Cause of Problem and Remedial Action Taken.* The high pressure line coming of transfer pump ruptured. The pump was shut down and the liner repaired. A vacuum truck was called to the facility & free waters were recovered.												
tank baπery. taken for anal report 11°H & results reflect 10/19/2007	The impacte ytical from the B-tex to be the TPH &	d area located the impacted a over the RRA B-tex to be un-	on the outs teas. Soil s I, for the si der the RR	ide of the berm me amples taken will te, a remediation v	easured be subm vork pla inal C-1	75'x 15'. Free itted to a secor n will be subm 41 form will b	standing water wa nd party lab & test itted to O.C.D The submitted to OC	as recover ted for TP he Chloric CD reques	ed by a variable. B-tex lies will be ting closu	e outside of the bern neuum truck. Soil sa & Chlorides. If anal e documented. When re for the release the	mples will be ytical results r final analytical	
I hereby certicall operators a environment failed to adeq	fy that the in ire required The accepta uately inves	formation give to report and/o ance of a C-14 tigate and reme	en above is r file certai l report by ediate cont	true and complete in release notificat the NMOCD mar ammation that pos	to the b rons and ked as "I e a threa	pest of my know perform corre Final Report" o it to ground wa	vledge and unders office actions for re loes not relieve th ter, surface water.	stand that eleases whee operator the human h	pursuant hich may r of liabili lealth or th	to NMOCD rules are endanger public hearty should their oper the environment. In the cor local laws and on local laws and	alth or the ations have addition,	
Signature: mie Stellfild						OIL CONSERVATION DIVISION						
Printed Name, Mike Stubblefield						Approved by DistrENWRONMENTAL ENGINEER						
Title: Environmental Regulatory Agent						Approval Date	11.1.07	<u> </u>	Expiration	Date: 12-31-2	7	
E-mail Addre	ss. mikes@g	ypenm.com			Conditions of	Approval:			Mached [
Date: 10/30 Attach Addit)/20007 100al Shee	ts If Necessar		505-748-4500			From C		_/	1		
- maon man	JIII DIICC	II 11000030I	,			w D	CUMPANTA	TOWN &	ر ا ا	()	L 11 19	