District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr Santa Fe, NM 87505 Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

						0	PERATOR		X	Initial Report	Final Report
Name of Company Yates Petroleum Corporation						Contact Mike Stubblefield					
Address 105 South 4th Street, Artesia, NM 88210						Telephone No 505-7484500 505-513-1712					
Facility Name Lotus "ALT" tank battery						Facility Typ	e Tank Battery		***************************************		
Surface Owner Federal Mineral Owner							· · · · · · · · · · · · · · · · · · ·	-	Lease 1	No. 034567	
1				LOCA	TIO	N OF REI	EASE		6	1	1970x
Unit Letter						South Line	Feet from the	East/W	est Line	County 🔏	
G	32	22s	32e	1980'	FNL		1980`	FEL	est Ling 828 87	rea Son	
								1	12/2	House Hone	57
Facility Name Lotus "ALT" tank battery Surface Owner Federal Mineral Owner Lease No. 3456											
									Volume Recovered 17.02		
Type of Release Produced water						Volume of Release >330 bbls Produced water			330 bbls produced water		
Source of Release High pressure discharge line at pump						Date and Hour of Occurrence 10/19/2007 4:00pm			Date and Hour of Discovery 10/19/2007 4:00pm		
'											
Was Immediate Notice Given? X Yes No Not Required						If YES, To Whom? Jerry Fanning left release report on after hour's office voice mail box.					
By Whom? Jerry Fammig, Jr.						Date and Hour 10/20/2007 12.40pm					
Was a Watercourse Reached?						If YES. Volume Impacting the Watercourse					
If a Watercourse was Impacted. Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.*											
The high pressure line coming of transfer pump ruptured. The pump was shut down and the liner repaired. A vacuum truck was called to the facility & free waters were recovered.											
Describe Area Affected and Cleanup Action Taken.* The affected area was the benned area of the tank battery & an area on the outside of the benned area of the											
										cuum truck. Soil sa	
										Chlorides. If anal	
										documented When	
results reflect the TPH & B-tex to be under the RRAL for the site, a final C-141 form will be submitted to OCD requesting closure for the release that occurred on											
10/19/2007. Depth to ground water >100°, Wellhead protection area > 1000°, Distance to surface water body > 1000° Site ranking 0											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations											
all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have											
failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
							OIL CON	ISERV	ATION	DIVISION	
Signature mie Stellfill						Ohuson					
Printed Name, Mike Stubblefield						Approved by DistrENVIRONMENTAL ENGINEER					
Title, Environ	mental Regu	llatory Agent			İ		: 11.1.07	Ĭ		Date: 12-31 - 2	7
E-mail Addres	ss: mikes@y	penm.com				Conditions of	Approval:			Mached	
	/20007			05-748-4500		Susur	From C	-(41	/	1	
Attach Addıtı	ional Sheet	s If Necessar	y			J la	cumzona C	- P	, <	_	10
						ه د	Mich San	riah D	7	- 4	アルルイ