State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised June 10, 2003

;

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release	Notification	and	Corrective	Action	
---------	--------------	-----	------------	--------	--

			(AMENDED)	
		OPERATOR	Initial Report	Final Report
Name of Company: Celero Energy	II, LP	Contact: Bruce Woodard		
Address: 400 W. Illinois, Suite 1601, Midland, TX 79701		Telephone No. 432-686-1883		
Facility Name: Drickey Queen Unit Salt Water Plant #1		Facility Type: Pit at Facility		
Surface Owner State	Mineral Ow	ner	Lease No.	
	LOCAT	TION OF RELEASE		

Unit Letter	Section\	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County	
1	3	14S	31E					Chaves	
							1		

Latitude <u>33.13043°</u> Longitude <u>103.80167°</u>

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Unknown	Volume Recovered None				
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery				
	Unknown	N/A				
Was Immediate Notice Given?	If YES, To Whom?					
Ycs No Not Required	Larry Johnson, NMOCD					
By Whom?	Date and Hour	(
Bruce Woodard						
Was a Watercourse Reached?	If YES, Volume Impacting the Wa	tercourse.				
🗌 Yes 🖾 No						
If a Watercourse was Impacted, Describe Fully.*	<u></u>					
······································						
N N						
Describe Cause of Problem and Remedial Action Taken.*	· · · · · · · · · · · · · · · · · · ·	A Para A				
This is an historic pit location. Celero acquired from Palisades and is in	he process of closing.					
Describe Area Affected and Cleanup Action Taken.*						
Pit has been dewatered and visually impacted soil removed as per Investi	gation and Characterization Plan. Soi	il borings have been placed in and around				
pit.	-	-				
I hereby certify that the information given above is true and complete to	he best of my knowledge and understa	and that pursuant to NMOCD rules and				
regulations all operators are required to report and/or file certain release t	notifications and perform corrective ac	ctions for releases which may endanger				
public health or the environment. The acceptance of a C-141 report by the	e NMOCD marked as "Final Report"	does not relieve the operator of liability				
should their operations have failed to adequately investigate and remedia						
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other						
federal, state, or local haws and/or/regutations.						
OIL CONSERVATION DIVISION						
OIL CONSERVATION DIVISION						
Signature: MMN 4		1				
	Approved by District ENAVERONMENTAL ENGINEER					
Printed Name: Bruce Woodard						
Title: Engineer	Approval Date: 11.16.07	Expiration Date: 3.31.08				
		1				
E-inail Address: bwoodard@celcroenergy.com	Conditions of Approval:	Attached				
Date: Phone: (432) 686-1883	FILE FINAL C. 141 W	Data By				
Attach Additional Sheets If Necessary		1 RD#1661				