

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

(AMENDED)

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Celero Energy II, LP	Contact: Bruce Woodard
Address: 400 W. Illinois, Suite 1601, Midland, TX 79701	Telephone No. 432-686-1883
Facility Name: Rock Queen Unit Tract #33 Tank Battery	Facility Type: Pit at Tank Battery

Surface Owner Private	Mineral Owner	Lease No.
-----------------------	---------------	-----------

**LOCATION OF RELEASE**

Unit Letter F	Section/ 23	Township 13S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Chaves
------------------	----------------	-----------------	--------------	---------------	------------------	---------------	----------------	------------------

Latitude 33.17611° Longitude 103.79611°

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release Unknown	Volume Recovered None
Source of Release	Date and Hour of Occurrence Unknown	Date and Hour of Discovery N/A
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson, NMOCD	
By Whom? Bruce Woodard	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

This is an historic pit location. Celero acquired from Palisades and is in the process of closing.

Describe Area Affected and Cleanup Action Taken.\*

Pit has been dewatered and visually impacted soil removed as per Investigation and Characterization Plan. Soil borings have been placed in and around pit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bruce Woodard	Approved by District Supervisor:  <b>ENVIRONMENTAL ENGINEER</b>	
Title: Engineer	Approval Date: <u>11.16.07</u>	Expiration Date: <u>3.31.08</u>
E-mail Address: bwoodard@celeroenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: _____ Phone: (432) 686-1883	<u>Submit Final C-141 w/data by</u>	

\* Attach Additional Sheets If Necessary

IRP# 1664