

# GW-4

RECEIVED

OCT 13 2003

Oil Conservation Division  
Environmental Bureau

## Groundwater Investigation Summary Report

ChevronTexaco Eunice #2 (North) Plant  
Eunice, Lea County, New Mexico

# REPORTS

Volume 2  
Figures

# 10/13/2003

October 9, 2003



PREPARED FOR

ChevronTexaco Exploration & Production  
Company



copyright © 2003



1004 N. Big Spring Street, Suite 300  
Midland, TX 79701-3383  
Tel 432 687 5400 Fax 432 687 5401

Drawn By  
H. Clardy

Drawing Date  
6 June 2003

File Location  
\\AutoCAD\\DWG\\ChevronTexaco\\North Eunice\\MT000700.004

File Name  
MT700417.dwg

Unique Number  
31-014-00456

Project Director  
M. Hagan

Area Manager  
A. Schmidt

Task Manager  
L. Markham

Technical Review  
S. Tischer

Project Number  
MT000700.0004

Figure  
51

ChevronTexaco Exploration & Production Company  
North Eunice Plant Quarterly Monitoring  
Shallow Groundwater Isoconcentration Map (December, 2002)  
Dissolved Hexavalent Chromium (mg/L)  
Eunice #2 (North) Gas Plant, Lea County, New Mexico

No.	Date	Revision Description	By	Ckd