

GW-4

RECEIVED

OCT 13 2003

Oil Conservation Division
Environmental Bureau

Groundwater Investigation
Summary Report

ChevronTexaco Eunice #2 (North) Plant
Eunice, Lea County, New Mexico

REPORTS

Volume 2
Figures

10/13/2003


October 9, 2003



Infrastructure, buildings, environment, communications

PREPARED FOR

ChevronTexaco Exploration & Production
Company



Copyright © 2003

No.	Date	Revision Description	By	Ckd



1004 N. Big Spring Street, Suite 300
Midland, TX 79701-3383
Tel 432 687 5400 Fax 432 687 5401

Drawn By
H. Clardy

Drawing Date
02 October 2003

File Location
\\AutoCAD\\DWG\\ChevronTexaco\\North Eunice\\MT000700.004

File Name
MT700421.dwg

Unique Number
31-014-00446

Project Director
M. Hagan

Area Manager
A. Schmidt

Task Manager
L. Markham

Technical Review
S. Tischer

Project Number
MT000700.0004

Figure
53

ChevronTexaco Exploration & Production Company
North Eunice Plant Groundwater Investigation
Shallow Groundwater Isoconcentration Map (December, 2002)
Chlorides (mg/L)
Eunice #2 (North) Gas Plant, Lea County, New Mexico