

RECEIVED

OCT 13 2003

Oil Conservation Division
Environmental Bureau

Groundwater Investigation Summary Report

ChevronTexaco Eunice #2 (North) Plant
Eunice, Lea County, New Mexico


REPORTS

Volume 2
Figures

10/13/2003

October 9, 2003

PREPARED FOR

ChevronTexaco Exploration & Product
Company

Copyright © 2003

No.	Date	Revision Description	By	Ckr



1004 N. Big Spring Street, Suite 300
Midland, TX 79701-3383
Tel 432 687 5400 Fax 432 687 5401

Drawn By
H. Clardy

Drawing Date	29 September 2003
--------------	-------------------

File Location
\\AutoCAD\\DWG\\ChevronTexaco\\North Eunice\\MT000700.004

File Name
MT700477.dwg

Unique Number
31-014-00537

Project Director
M. Hagan

Area Manager
A. Schmidt

Task Manager	L. Markham
--------------	------------

	Technical Review S. Tischer
--	--------------------------------

Project Number
MT000700.0004

Figure 73

ChevronTexaco Exploration & Production Company
North Eunice Plant Groundwater Investigation
Shallow Groundwater Isoconcentration Map (May, 2003)
Chlorides (mg/L)
Eunice #2 (North) Gas Plant, Lea County, New Mexico