

# GW-4

RECEIVED

OCT 13 2003

## Groundwater Investigation Summary Report

Oil Conservation Division  
Environmental Bureau

ChevronTexaco Eunice #2 (North) Plant  
Eunice, Lea County, New Mexico

# REPORTS

Volume 2  
Figures


# 10/13/2003

October 9, 2003




PREPARED FOR

ChevronTexaco Exploration & Production  
Company



- Explanation**
- Monitor Well Location
  - ▲ Recovery Well Location
  - \* Water Supply Well Location
  - 3,336.04' Sediment Level Elevation
  - NR Not Recorded
  - 3,335.00' Sediment Level Contour
  - Contour Interval — 5.0 Feet  
Except Where Noted
  - - - Practical Boundary Separating Fully-Penetrating Versus Partially-Penetrating Well Completions



No.	Date	Revision Description	By	Ckd

1004 N. Big Spring Street, Suite 300  
Midland, TX 79701-3383  
Tel 432 687 5400 Fax 432 687 5401

Drawn By H. Clardy	Drawing Date 4 June 2003	File Location \\AutoCAD\DWG\ChevronTexaco\North Eunice\Mt000700.004	File Name MT700412.Dwg	Unique Number 31-014-00452	Project Director M. Hagan	Area Manager A. Schmidt
ChevronTexaco Exploration & Production Company North Eunice Plant Quarterly Monitoring				Task Manager L. Markham	Technical Review S. Tischer	
Top of Triassic Sediments Map				Project Number MT000700.0004	Figure 78	
Eunice #2 (North) Gas Plant, Lea County, New Mexico						

copyright © 2003