

# GW-4

RECEIVED

OCT 13 2003

## Groundwater Investigation Summary Report

Oil Conservation Division  
Environmental Bureau

ChevronTexaco Eunice #2 (North) Plant  
Eunice, Lea County, New Mexico

# REPORTS

Volume 2  
Figures

# 10/13/2003

October 9, 2003




Infrastructure, buildings, environment, communications

PREPARED FOR

ChevronTexaco Exploration & Production  
Company



- Explanation**
- Monitor Well Location
  - ▲ Recovery Well Location
  - ★ Water Supply Well Location
  - 3,377.78' Groundwater Elevation
  - NC Not Collected
  - 3,377.00' Groundwater Elevation Contour  
Contour Interval - 0.50'
  - - - Practical Boundary Separating Fully-Penetrating Versus Partially-Penetrating Well Completions



No.	Date	Revision Description	By	Ckd



1004 N. Big Spring Street, Suite 300  
Midland, TX 79701-3383  
Tel 432 687 5400 Fax 432 687 5401

Drawn By  
G. Shick

Drawing Date  
9 June 2003

File Location  
LDWG\ChevronTexaco\North Eunice\Mt000700.004

File Name  
MT700458.Dwg

Unique Number  
31-014-00379

Project Director  
M. Hagan

Area Manager  
A. Schmidt

ChevronTexaco Exploration & Production Company  
North Eunice Plant Remediation

Task Manager  
L. Markham

Technical Review  
S. Tischer

Hydraulic Gradient Map (May, 2001)

Project Number  
MT000700.0004

Figure  
80

Eunice #2 (North) Gas Plant, Lea County, New Mexico

copyright © 2003