District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action														
						OPERATOR								
						Contact BRADLEY BLEVINS								
						Telephone No. 505-391-1462								
Facility Name Hudgens SWD #1						Facility Type Disposal Well								
Surface Owner Mineral Owner						Lease No.								
		LO	CATION OF	REI	EASÉ A	PI #30-0	025-29	9712	· ,					
										st/West Line County				
J	11 16S	36E	1980	SOU	TH	1980		EAS	T	LEA				
	(1.21)	Longitude												
LatitudeLongitude NATURE OF RELEASE														
Type of Rele	ease Produced water	Volume of Release 40 BBLS Volume Recovered 32 BBLS												
Source of Release A valve froze and popped the ball valve						1/1/08 7:00 A.M. 1/01/08 1					0:00 A.M.			
						Date and Hour of Occurrence Date and Hou						<i>'</i>		
Was Immediate Notice Given? Yes No Not Required If YES, To Whom?														
							· · · · · · · · · · · · · · · · · · ·							
By Whom?						Date and Hour If YES, Volume Impacting the Watercourse.								
Was a Watercourse Reached?						11 1 E.S., volume impacting the watercourse.								
If a Watercourse was Impacted, Describe Fully.*														
n a watercourse was impacted, Describe runy.														
						-								
	Describe Cause of Problem and Remedial Action Taken.*													
A valve freeze and popped the ball valve releasing produced water inside the tank battery containment. Vaccum trucks dispatched to recover as much of the produced water as possible, recovered 32 bbls.														
recover as i	nuch of the produced v	vater as pe	ossible, recovere	ed 32 b	bls.									
Describe Area Affected and Cleanup Action Taken.*														
	-					maad an 1	/2 /00	Cail	uill be eve	aveted a	bolama	and		
32 BBLS of produced water was recovered. Soil remediation activities commenced on 1/3/08. Soil will be excavated, sampled, and backfilled upon approval from NMOCD.														
ouckinica (ipon approvar nom ren	iocs.												
I hereby cert	ify that the information g	iven ahove	is true and comp	lete to t	he best of my	knowledge	e and ur	ndersta	nd that purs	suant to N	IMOCD r	ules and	\dashv	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger														
public health	or the environment. The	e acceptanc	ce of a C-141 repo	rt by th	e NMOCD m	arked as "I	Final Re	port" c	loes not reli	ieve the c	perator o	f liability	.	
should their	operations have failed to onment. In addition, NMO	adequately	investigate and restance of a C-141	emediai	te contaminati	on that pos	se a thre	at to g	round water	r, surtace	water, hu	ıman healti v other	a	
	e, or local laws and/or reg		nance of a C-141	героп с	ioes not renev	e the opera	101 01 1	cspons	ionity for c	omphane	e with an	y other		
OIL CONSERVATION										DIVIS	SION			
Signatures	(0:1, P.7 for	r Chasens	naka Onaratina	Inc										
Signature: Clyff. Tunan for Chesapeake Operating, Inc.						approved by District Supervisor:				"	.0			
Printed Name: CLIFF P. BRUNSON						.,			Mus	s U	zel	i our		
Title: PR	ESIDENT				Approval Dat	ei: ///	10	8	Expiration	Date:	4/	16/08	>	

Conditions of Approval:

Date: 1/09/08

E-mail Address: CBRUNSON@BBCINTERNATIONAL.COM

Phone: 505-397-6388

RP#1712

Attached, \square

^{*} Attach Additional Sheets If Necessary