

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>Pogo Producing Co.</u>	Contact <u>PAT ELLIS</u>
Address <u>P.O. Box 10340 Midland, TX 79702</u>	Telephone No. <u>432 685-8100</u>
Facility Name <u>Cotton DRAIN Unit # 9</u>	Facility Type <u>MAIN injection line</u>

Surface Owner	Mineral Owner <u>NEW MEXICO</u>	Lease No. <u>LC-061300</u>
---------------	---------------------------------	----------------------------

## LOCATION OF RELEASE

API # 30025 08222

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>E</u>	<u>22</u>	<u>25S</u>	<u>32E</u>	<u>1980</u>	<u>North</u>	<u>660</u>	<u>West</u>	<u>Lea</u>

300'

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release <u>Produced WATER</u>	Volume of Release <u>40 BBLs</u>	Volume Recovered <u>30 BBLs</u>
Source of Release <u>Injection line LEAK</u>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>1-16-08 10:45 AM</u> <u>BLM - TRISH BADBEAR - phone message</u> <u>OCD - Cindy HARRA - phone message</u>	
By Whom? <u>Johnny Burnett</u>	Date and Hour <u>1-16-08 11:00 AM</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

LEAK OCCURRED DUE TO CORROSION OF MAIN INJECTION LINE. UNCOVERED LINE AND REPAIRED INJECTION LINE.

Describe Area Affected and Cleanup Action Taken.\*

FOREMAN CALLED OUT VACUUM TRUCKS TO PICK UP PRODUCED WATER. CALLED HIGHLANDER ENVIRONMENTAL TO SAMPLE SOILS AND DEVELOP REMEDIATION WORKPLAN.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: Patrick L. EllisPrinted Name: PATRICK L. ELLISTitle: EHS SUPERVISORE-mail Address: ellis.p@pogoproducing.com  
(432)Date: 1-22-08Phone: 685-8100Approved by District Supervisor: Chris WilliamsApproval Date: 1/25/08Expiration Date: 4/26/08

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

RP# 1757