

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name SEMU Permian Well #77	Facility Type Oil Well

Surface Owner BLM	Mineral Owner BLM	Lease No. LC 031670B
-------------------	-------------------	----------------------

LOCATION OF RELEASE API# 30025077980000

Unit Letter L	Section 18	Township 20S	Range 38E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line West	County Lea
---------------	------------	--------------	-----------	--------------------	------------------------	-------------------	---------------------	------------

Latitude N 32 34.186 Longitude W 103 12.042

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 34	Volume Recovered 30
Source of Release Flowline	Date and Hour of Occurrence 1/2/08 3:35 pm	Date and Hour of Discovery 1/2/08 8am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD & BLM	
By Whom? Jesse Sosa	Date and Hour 1/2/08 3:35 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED

JAN - 3 2008



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
There was an accidental discharge of 34 BPW from a 2 inch flowline. MSO shut down beam and isolated leak.

HOBBS OCD

Describe Area Affected and Cleanup Action Taken.\*  
MSO called out vacuum truck and recovered 30 BPW. Affected area of 25 feet X 85 feet was all on caliche road.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Approved by District Supervisor:  ENVIRONMENTAL ENGINEER	
Title: HSER Lead	Approval Date: 1-8-08	Expiration Date: _____
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval:	
Date: 01/02/2008 Phone: (505)391-3126	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

\* Be sure and add  
API# to spill report  
if applicable jhx  
pat

API# 1704  
3119