

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 <sup>TH</sup> STREET	Telephone No 505.748.1471	
Facility Name CLEARY AKC FEDERAL 2	API Number 30-025-31926	Facility Type SWD
Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No


LOCATION OF RELEASE

Unit Letter D	Section 17	Township 22S	Range 32E	Feet from the 330	North/South Line NORTH	Feet from the 330	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.39796 Longitude 103 70381

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 150 B/PW	Volume Recovered 150 B/PW
Source of Release WATER LEG ON TANK	Date and Hour of Occurrence 11/12/07 05 00 HRS	Date and Hour of Discovery 11/12/07 08.00 HRS
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD DISTRICT I PAT RICHARDS VIA VOICE MAIL AND FOLLOW UP E-MAIL	
By Whom? SHERRY BONHAM	Date and Hour 11/12/07 10:40 HRS	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* PUMP UNABLE TO KEEP UP WITH WATER FLOW COMING IN. SHUT MAIN VALVE.		
Describe Area Affected and Cleanup Action Taken.* TOTAL DISCHARGE CONTAINED WITHIN A 30' X 100' LINED BERMED AREA. ALL DISCHARGED FLUIDS RECOVERED BY VACUUM TRUCK NO ADDITIONAL REMEDIAL ACTIONS NECESSARY. REQUESTING CLOSURE TO INCIDENT. FINAL REPORT.  DEPTH TO GROUND WATER <u>&gt;100'</u> ; WELLHEAD PROTECTION? <u>NO</u> , DISTANCE TO SURFACE WATER: <u>&gt;1000'</u> . SITE RANKING <u>0</u>		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sherry Bonham</i>	OIL CONSERVATION DIVISION	
Printed Name: Sherry Bonham	Approved by District Supervisor: <i>Johnson</i>	
Title: Environmental Regulatory Agent	Approval Date: <u>2-4-08</u>	Expiration Date: <u>      </u>
E-mail Address: sherryb@ypcnm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: November 16, 2007	Phone: 505.748.1471	

\* Attach Additional Sheets If Necessary

RP#1775