District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr. Senta Fe. NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505

nSEB0803630534

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

_	_	_			
$\overline{}$	2	2	8	05	1

Release Notification and Corrective Action OPERATOR

3001528203 01					OPE	ERATOR	☑ Initi	ial Report		Final Report			
Name of Company: Americo Energy Resources						Contact: D	on Gray						
Address: 7575 San Filipe Ste 200, Houston Tx 77063						Telephone No.: 713-984-9700							
Facility Name: ESU # 72 -						Facility Type: Injection water line							
Surface Owner: BLM Mineral Own						er: BLM			Lease No.: LC-03473				
LOCATION OF RELEASE													
									/West Line County				
L	, , , , , ,		South		1150'	West		Eddy					
Latitude <u>32.701350</u> Longitude <u>103.844550</u>													
NATURE OF RELEASE													
Type of Rele	ase: Produ	ced water and			Volume of Release: ~505 bbl Volume Recovered: 240 bbl								
Source of Release: 2' Trunk Line						Date and H	our of Occurrenc	Date and Hour of Discovery: 10/5/07					
Was Immedia	ate Notice C	Given?				If YES, To	Whom?		10/0/07				
			Yes X	No Not Requi	ired								
By Whom?						Date and Hour:							
Was a Water	Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume Impacting the Watercourse.							
If a Watercou	irse was Im	pacted, Descri	be Fully.*			<u> </u>				······································			
N/A												}	
Describe Cause of Problem and Remedial Action Taken.* Failure of the trunk line. The line was closed in.													
7 unare or une	traine mio.	The line was	ciosca iii.									-	
Describe Area	Describe Area Affected and Cleanup Action Taken.*												
The spill affected approximately 4,732 sq.ft. SESI has been contacted to delineate and compose workplan													
I hereby certif	v that the in	formation giv	en above	is true and compl	ete to f	he best of my	enowledge and un	nderstan	d that purs	uant to NMC	CD ru	les and	
regulations all	l operators a	are required to	report an	d/or file certain re	lease n	otifications an	d perform correct	ive acti	ons for rele	ases which n	nay end	danger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state,													
1 - /						OIL CONSERVATION DIVISION							
Signature:	[][][]	v h	10										
Printed Name: Jerri Lee						Approved by District Supervisor: TGum by \$3							
Title: Consultant/SESI						Approval Date: Expiration Date:							
E-mail Addres	ss: office@	sesi-nm.com			'	Conditions of Approval: RENEDIATION Attached Plan Due 3-5-08							
Date: 1-31-			575-397-0	510		Plan	Due 3	5-5	<u>-08</u>				
Attach Additi			ry							RP-	12)	
CCD A	1171.	20-1							\sim	ンドトー	104	<u>~</u>	