


GW - 004

# 2006 MONITORING REPORTS

03/12/2007



- Explanation**
- MW046 + Monitoring Well Location
  - <6\* BTEX Concentration (ug/L)
  - \* Value not used to generate contours
  - Recovery Well Location
  - Injection Well Location
  - Water Supply Well Location
  - BTEX Isoconcentration Contour
  - Inferred Isoconcentration Contour

Note: It is believed previous molasses injection resulted in laboratory interferences and elevated detection limits in affected wells.

|                                                                                                        |                                                      |                  |                                                      |              |                      |
|--------------------------------------------------------------------------------------------------------|------------------------------------------------------|------------------|------------------------------------------------------|--------------|----------------------|
| <br>2321 Club Meridian Drive, Suite E<br>Okemos, Michigan<br>PHONE: (517) 349-9499 FAX: (517) 349-6863 | FOR:<br>EUNICE NORTH GAS PLANT<br>EUNICE, NEW MEXICO |                  | BTEX ISOCONCENTRATION MAP<br>(JANUARY/FEBRUARY 2006) |              | FIGURE:<br><b>21</b> |
|                                                                                                        | JOB NUMBER:<br>89CH.49410.07                         | DRAWN BY:<br>RDT | CHECKED BY:                                          | APPROVED BY: | DATE:<br>05/18/06    |