

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company	Saber Resources, Inc.	Contact	Doug Keathley
Address	400 W. Illinois, Suite 950, Midland, TX 79701	Telephone No.	(432) 685-0169
Facility Name	Pitts-Kendrick #1	Facility Type	Tank Battery

Surface Owner	Tommy Burress	Mineral Owner	Fee Lease – Various Owners	API No.	30-025-31152
---------------	---------------	---------------	----------------------------	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	12S	38E	1500	South	1650	East	Lea

Latitude N 33 deg. 30457' Longitude W 103 deg. 11613'

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	5 bbl	Volume Recovered	3
Source of Release	Separator	Date and Hour of Occurrence	1/13/08 @ unknown time	Date and Hour of Discovery	1/14/08 @ 1330
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	<b>RECEIVED</b>		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<b>MAR 03 2008</b>		

If a Watercourse was Impacted, Describe Fully.\*

**HOBBS OCD**

Describe Cause of Problem and Remedial Action Taken.\*



Separator overflowed. Spill was contained on wellpad. Approximately 3 bbl of fluid was removed from the site by vacuum truck. Impacted soil was excavated from the current spill area, as well as historical spill areas, and hauled to an NMOCD approved disposal facility.

Describe Area Affected and Cleanup Action Taken.\*

An area approximately 52' x 70' within the well pad area was excavated until final confirmation samples reported chloride concentrations less than 250 mg/kg. The area on the wellpad was backfilled with clean soil.

Depth to groundwater is at approximately 32' bgs.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Doug Keathley	Approved by District Supervisor:  by MW	
Title: Vice President of Operations	Approval Date: 3/3/2008	Expiration Date:
E-mail Address: Doug@SaberResources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/25/08 Phone: (432) 685-0169		RP# 1797

\* Attach Additional Sheets If Necessary

f COH080633302