

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised January 1, 2008

Submit 1 Copy to appropriate
District Office

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company DCP Midstream, LP	Contact Johnnie Bradford
Address 10 Desta Drive, Suite 400 W, Midland, TX., 79705	Telephone# & E-mail 432.620.4166 jbradford@dcpmidstream.com
Facility Name: Hat Mesa Gathering (line# C23-10-1-10-3-7)	Facility Type Pipeline

Surface Owner	Mineral Owner	Well API No.
---------------	---------------	--------------

LOCATION OF RELEASE

Unit Letter	Section 30	Township 21S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.2684 N Longitude 103.4272 W

NATURE OF RELEASE

Type of Release Gas and Oil	Volume of Release Gas 2038.4 mcf, Oil 3 bbls	Volume Recovered 0 gas, 5-7 yd3 of soil
Source of Release Open ended pipeline due to contractor error	Date & Hour of Occurrence 03/04/2008	Date & Hour of Discovery
Was Immediate Notice Given OCD? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom @ OCD? Chris Williams	
By Whom? Johnnie Bradford	Date and Hour 03/05/2008 1100	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse NA	

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

NA

MAR 10 2008

Describe Cause of Problem and Remedial Action Taken. (If water spilled, give Chloride content)*

While working around DCPMs 4" pipeline, a contractor was using a bull dozer to build a pad for another company when the pipe was struck and leaked half. Gas vented for approximately 3 hours and 15 minutes, until temporary repairs could be made to contain the release. Once contained, DCPM contracted a service company to cap the pipeline properly.

HOBBS OCD

Describe Area Affected, Dimensions, and Cleanup Action Taken.*

The area of soil impacted was approximately 15 X 30. The contamination was on the surface only; therefore, affected area was scrapped with all soils placed on plastic until proper sampling could be conducted. Once approval is granted, the soil (approximately 5-7 yd3) will be disposed at the CRI land farm in Lea County, NM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>Johnnie Bradford</i>		OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford		Approved by District Supervisor: <i>Chris Williams</i>	
Title: Sr. Environmental Specialist		Approval Date: 3/10/08	Expiration Date: 5/10/08
E-mail Address: jbradford@dcpmidstream.com		Conditions of Approval: <i>Mud to receive analytical before final closure.</i>	
Date: 03/10/08	Phone: 432.620.4166	RP# 1809	

* Attach Additional Sheets If Necessary

f C040807127723