timated Distribution

Group, Inc.

| Scale: 1" = 100" | Prep By: JDJ | Checked By: BB | January 13, 2003 | ETGI Project #: EOT2074C

TPH Soil Contamination Below 15' BGS EOTT Energy Pipeline, LP Jimmy B. Cooper Lea County, NM

Estimated Lateral Extent of Contaminant Fence

Indicates Soil Boring Location

Abandoned Water Well Location

Domestic Well Location
Monitor Well Location
Production Well
Irrigation Well Location

**AP-19** 

## ASSESEMENT REPORT

**Cont. of Two Drawings** 

YEAR(S): Jan. 17, 2003