State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rele	ease Notific	-	n and			ctio	n ,				
						OPERATOR				Initial Report 🔲 Final Report				
Name of Company Apache Corp							Contact Natalie Gladden						·	
							Telephone No. 575-390-4186							
Facility Name EBDU Battery #5(nearest well EBDU #63)							Facility Type Battery							
Surface Owner Lucille Bryant Mineral Owner							Apache Corp				Lease No. 30-025-38234			
·····				LOCA	TIC	DN OF RELEASE								
Unit Letter	Section	Township	wnship Range Feet from the No		Nort	rth/South Line Feet from the E			East/	East/West Line County				
J	14 21S 37E 1485		Sout	h Line	Line 2310			Line	Lea					
Latitude N32 deg 28.954' Longitude W103 deg 07.874'														
Type of Release Oil/Wtr							Volume of Release 5bbls				Volume Recovered 1bbl			
Source of Release 2" hammer union							Occurred 5/5/08				Discovery 5/5/08 11:30			
Was Immediate Notice Given? Yes D No D Not Required							If YES, To Whom? d Larry Johnson at 11:35 am							
By Whom? Natalie Gladden							Date and Hour: 05/05/08 11:35am							
Was a Watercourse Reached?								lume Impactine						
Yes 🛱 No										REIN				
If a Watercou	rse was Im	pacted, Descr	ibe Fully.'	k					6-6	Je v	ied)			
Describe Cau	an of Brobl	am and Pama	dial A atio	n Takon *						' 1 Z 200				
				covered 1bbl of fl	uid.					BS (JÜL	<u>}</u>		
Describe Area Affected and Cleanup Action Taken.* Release was contained inside berms and Hydro-tech came to location and picked up all contaminates and hauled to Sundance. Samples will be taken inside berm area. And pea-gravel will be installed in berm area.														
regulations al public health should their c	l operators or the envir perations h iment. In a	are required to conment. The ave failed to a ddition, NMC	o report an acceptanc idequately ICD accep	is true and compl id/or file certain re- ee of a C-141 repo investigate and re- tance of a C-141 r	elease rt by the emedia	notification he NMOCI nte contami	ns an D ma inatic	d perform correc arked as "Final R on that pose a thr	tive act eport" (eat to g	tions for release does not release round water	eases which ieve the ope r, surface wa	may er rator of ater, hu	ndanger f liability man health	
Signature addie Caladen							OIL CONSERVATION DIVISION							
Printed Name: Natalie Gladden							Approved by District SUPPRIONMENTAL ENGINEER							
Title: EH&S Environmental Tech						Approval	Date	5.14.0g	3	Expiration	Date: 7.	14.0	8	
E-mail Address: Natalie.gladden@apachecorp.com							is of	Approval:			1			
Date: 5-12-08 Phone: 505-390-4186							MIT	FIL C. H	مامو ا	ec By	Attached		tese	
* Attach Addit				······					(*		<u> </u>			
			ŧ	- Cotta	08	135	3	8216					1990	