

1625 N French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources

Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | | |
|-----------------|--|---------------|-------------------------|
| Name of Company | COG OPERATING LLC | Contact | Kanicia Carrillo |
| Address | 550 W. Texas, Suite 1300 Midland, TX 79701 | Telephone No. | 432-685-4332 |
| Facility Name | Leaker CC State Battery | Facility Type | Oil Well - Tank Battery |

| | | |
|---------------|---------------|-----------|
| Surface Owner | Mineral Owner | Lease No. |
|---------------|---------------|-----------|

LOCATION OF RELEASE

30-025-38589

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| H | 16 | 17S | 32E | 1650 | North | 990 | East | Eddy |

Latitude _____ Longitude _____

NATURE OF RELEASE



| | | | | | |
|-----------------------------|---|---|-------------------------|----------------------------|-----------------|
| Type of Release | Produced Water | Volume of Release | 10 bbls | Volume Recovered | 10 bbls |
| Source of Release | Plugged filter pot | Date and Hour of Occurrence | 06/15/08 Approx 12:00pm | Date and Hour of Discovery | 06/15/08 7:30am |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Cindy Herrera | | |
| By Whom? | Kanicia Carrillo | Date and Hour | 06/16/08 3:20pm | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
 Plugged filter pot. We unplugged pot and changed out filters.

Describe Area Affected and Cleanup Action Taken.*
 10' x 20' area. We are currently removing all fluid from the ground and will excavate and remove contaminated soil. Highlander Environmental will send report and soil samples

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Kanicia Carrillo | Approved by District Supervisor:  | |
| Title: Regulatory Analyst | Approval Date: 6/23/08 | Expiration Date: 6/23/08 |
| E-mail Address: kcarrillo@conchoresources.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 06/16/08 Phone: 432-685-4332 | | 1 RD-1881 |

* Attach Additional Sheets If Necessary

2040816939987