

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No 1004-0135
Expires July 31, 1996

OCD-ARTESIA

JUN 16 2008

OCD-ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No LC-065421
2. Name of Operator Cimarex Energy Co. of Colorado		6. If Indian, Allottee or Tribe Name
3a. Address PO Box 140907; Irving, TX 75014-0907		7. If Unit or CA/Agreement, Name and/or No. NM-111029
3b. Phone No. (include area code) 972-401-3111		8. Well Name and No. Bradley 14 Federal Com No. 1
4. Location of Well (Footage, Sec., T, R, M., or Survey Description) 1650' FNL & 990' FWL 14-24S-26E		9. API Well No 30-015-32672
		10. Field and Pool, or Exploratory Area White City; Penn (Gas)
		11. County or Parish, State Eddy County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, included estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- Well currently has CIBP @ -10610' w/ 2-sx cmt covering Morrow perfs @ -10650'-11832' and CIBP @ -10130' w/ 2-sx cmt covering Cisco-Canyon perfs @ 10188'-10301.' TOC @ 10115.'


On 02-20-08, tested casing to 590 psig for 40 minutes, casing held. Danny Emerson, Cimarex field representative, left a message with BLM receptionist notifying them of the test. Test was not witnessed.

Request TA status due to horizontal Cisco-Canyon and/or horizontal Delaware potential. Cimarex has recently begun a horizontal Delaware program in the White City; Penn area.

*see attached
(30 days)*

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Becky Nogelmeier		Title Operations Assistant
Signature 		Date JUN 12 2008
ACCEPTED FOR RECORD		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		
Approved by Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA		Office
Conditions of Approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction		
(Instructions on reverse)		

ACCEPTED FOR RECORD	
Date JUN 12 2008	
WESLEY W. INGRAM PETROLEUM ENGINEER	



**Bradley 14 Federal Com 1
Cimarex Energy Co. of Colorado
June 12, 2008
Conditions**

- 1. Notice of intent should have been sent requesting CIT with justification for request to TA well. Operator to provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.**
- 2. Please submit a sundry requesting CIT with justification within 30 days.**
- 3. BLM to be notified at 575-361-2822 for Eddy County a minimum of 4 hours prior to a CIT.**
- 4. Inadequate cement on CIBP at 10610'. BLM requirements state that 35' of cement bailed or 25 sacks pumped. NOI in 4/05/08 stated that 35' of cement would be placed on CIBP. Two sacks would get a maximum of 20'.**
- 5. Inadequate cement on CIBP at 10130'. BLM requirements state that 35' of cement bailed or 25 sacks pumped.**
- 6. If additional cement is not added at this time, it will be necessary to do it when the well is plugged, which could mean drilling out more than one CIBP.**
- 7. See attached conditions for temporary abandonment.**

WWI 061208

BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

Temporary Abandonment of Wells on Federal Lands
Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows

1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
2. Describes the temporary abandonment procedure.
3. Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.
2. A procedure to plug and abandon the well.