.

\$

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003 JUL 18 2008 Submit 2 Copies to appropriate OCD-ARTESIA District Office in accordance with Rule 116 on back

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Santa	Fe, NM 87505 side of form
Release Notification and Corrective Action	
i SEB082-1852969	
NSEB0821852642 154903	OPERATOR X Initial Report Final Report
Name of Company St. Mary Land & Exploration Co. Address 3300 N. A St. Bldg 7, Suite 200, Midland, TX 79705	Contact Tom Morrow Telephone No. 432-688-1773
Facility Name ESDU Injection Station	Facility Type Injection Station
Tacinty Name ESDO injection Station	
Surface Owner Bureau of Land Management Mineral Owner	er Bureau of Land Management Lease No.
<i>30 015 31350</i> LOCATION OF RELEASE	
Unit Letter ASection 24Township 18SRange 31EFeet from the NoNo	rth/South Line Feet from the East/West Line County
LatitudeLongitude	
NATURE OF RELEASE	
Type of Release Produced Wtr.	Volume of Release 500 bbls Volume Recovered 410 bbls
Source of Release Fire destroyed water tanks & gun barrell	Date and Hour of OccurrenceDate and Hour of Discovery7/16/086:00 AM7/16/086:00 AM
Was Immediate Notice Given?	If YES, To Whom?
X Yes 🗌 No 🗌 Not Require	
By Whom? Bill Hearn	Date and Hour 5/30/08 10:01AM
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.
If a Watercourse was Impacted, Describe Fully.*	
Describe Cause of Problem and Remedial Action Taken.* CAUSE: Lightening struck injection station burning down (3) 500 bbl fiberglass suction tanks and scorching 750 bbl fiberglass gun barrel. Fill lines were broken away from tanks causing spill. REMEDIAL ACTION: Notified all oil companies and shut-in all off lease water entering facility.	
Describe Area Affected and Cleanup Action Taken.* AFFECTED AREA: 85' X 45' = 3825 sq. ft. & 100' X 95' = 9500 sq. ft. Total = 13325 sq. ft. (Pasture Land) CLEANUP ACTION: Picked up standing fluid w/vacuum truck. Waiting or orders from BLM/OCD for further cleanup remediation action.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Signature: Donna Huddlisten	OIL CONSERVATION DIVISION
Printed Name: Donna Huddleston	Approved by District Supervisor: TGum by SB
Title: Production Tech	Approval Date: 8-5-08 Expiration Date:
E-mail Address: dhuddleston@stmaryland.com	Conditions of Approval:
Date: 07/17/2008 Phone: 432-688-1789	Attached D 2RD-208

* Attach Additional Sheets If Necessary

SEB 0821853045



Bill Richardson Governor

Joanna Prukop Cabinet Secretary Reese Fullerton Deputy Cabinet Secretary Mark Fesmire Division Director Oil Conservation Division



CERTIFIED MAIL—RETURN RECEIPT REQUESTED 7007 2680 0001 6451 0779

August 5, 2008

St. Mary Land & Exploration Co 3300 N A St. Bldg 7, Suite 200 Midland, TX 79705

RE: East Shugart Delaware Unit 020 A-24-18S-31E 30-015-31350 Eddy County, New Mexico 2RP-208

Dear Operator:

This office is in receipt of your C-141 regarding the produced water release at this facility.

NMOCD Rule 19.15.3.116 states in part, "...The responsible person must complete **division approved corrective action** for releases which endanger public health or the environment. Releases will be addressed in accordance with a <u>remediation plan</u> submitted to and approved by the division or with an abatement plan submitted in accordance with Section 19 of 19.15.1 NMAC."

Information and tools for proper corrective action may be found in the Environmental Handbook on our web site at the following link: <u>http://www.emnrd.state.nm.us/ocd/documents/7C_spill1.pdf</u>

The following actions are **required** to be addressed in the **remediation plan**:

- Determine the horizontal and vertical delineation of the spill by sampling.
- Prepare a sketch of the site indicating where and at what depths the samples were taken.
- Submit laboratory results of sampling as well as the proposed remediation with the plan.

August 5, 2008 Page 2

.

Remediation requirements may be subject to other federal, state, and local laws or regulations.

Within 30 days, **on or before September 8, 2008,** completion of a remediation work plan should be finalized and submitted to the Division summarizing all actions taken or to be taken to mitigate environmental damage related to the leak, spill or release for approval.

Please be advised that NMOCD acceptance and/or approval of documents or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance and/or approval of documents or work plans do not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If I may be of further assistance with this matter or should you have any questions, please feel free to contact me.

Sincerely,

Sherry Bonham NMOCD District II, Artesia (505) 748-1283 ext 109 E-mail: <u>sherry.bonham@state.nm.us</u>