

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Rice Operating	Contact Tony Grieco
Address 122 W. Taylor St., Hobbs, NM 88240	Telephone No. (575) 393-9174
Facility Name BD	Facility Type Salt Water Gathering System

Surface Owner MILLARD DECK EST	Mineral Owner	Lease No.
---------------------------------------	---------------	-----------

LOCATION OF RELEASE

API # **30-025-06686-00-00**

Unit Letter K	Section 20	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude **32°27.658N** Longitude **103°11.209W**

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 38 bbls	Volume Recovered 0 bbls
Source of Release PIPELINE	Date and Hour of Occurrence 1/18/06	Date and Hour of Discovery 1/18/06 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? PAUL SHEELEY- LEFT MESSAGE	
By Whom? JENNIFER JOHNSON	Date and Hour 1/18/06 4:40 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A gasket failed. The gasket was replaced as a permanent repair.**

Describe Area Affected and Cleanup Action Taken.*

Approximately 2550 sq ft affected. On 2/15/06 a total of 24 yds of impacted material were scraped from the site and properly disposed at Sundance disposal facility in Eunice. Additional delineation was conducted using a hand auger on 1/12/07. On 6/12/08 24 yds of clean soil were imported and spread, and the entire area was seeded with 1 lb of Lea County Mix seed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Tony Grieco		Approved by District Supervisor: 	
Title: Environmental Tech		Approval Date: 7/14/08	Expiration Date: 7/14/08
E-mail Address: tgrieco@riceswd.com		Conditions of Approval:	
Date: 6/12/08 Phone: (575) 393-9174		Attached <input type="checkbox"/> IRP#1843	

* Attach Additional Sheets If Necessary