District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141

Revised October 10, 2003

Release Notification and Corrective Action

			OPE	ERATOR Initial Report Final					Final Report		
Name of Company: Targa Midstream Services L P						Contact: James Lingnau 505.394.2534, Chuck Tolsma 505.631.6026					
Address: PO Box 1909 Eunice, NM 88231						Telephone No. (505) 394-2534					
Facility Name: Eunice Gathering System						Facility Type					
Surface Owner: Deck Estate Turner Road Mineral Owner:						Lease No. 30,025, 26444,0000					
Surface OW	ner: Deck	Estate Turne	r Koad	Milleral C	Lease 110. 30.023. 20 14 1.00 5						
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/We	st Line	County	,
E	28	21S	37E		8					T	
	<u> </u>						Lea				
Latitude <u>32.28.605 N</u> Longitude <u>103.10.737W</u>											
NATURE OF RELEASE											
Type of Rele	ase: Gas an	d Produced Li	iquids		Volume of	Volume of Release: Unknown Volume Recovered: None					
Source of Release: 4" or 6" Pipeline Failure							Date and Hour of Occurrence: Date and Hour of Discovery				
Source of Release. 4 of o 1 ipenile i affare						Unknown Unknown					
Was Immediate Notice Given?						If YES, To Whom?					
		☐ Ye	s 🗶 1	No 🔲 Not Re							
By Whom?						Date and Hour					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
			× No								
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Broblem and Remedial Action Taken *											
Describe Cause of Problem and Remedial Action Taken. * A Four inch or Six inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Line was repaired and possibly											
contaminated soil used for backfill.											
Describe Are	a Affected	and Cleanup A	Action Tak	ten.*		<u> </u>					
	cavate and	sample the are	a of conta	mination and ren	nove ar	y contaminate	ed soil. The area v	vill be clea	aned and	tested pe	er OCD
Targa will excavate and sample the area of contamination and remove any contaminated soil. The area will be cleaned and tested per OCD Guidelines.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water,											
human health	or the envi	ronment. In a	aneu io au addition, N	IMOCD acceptan	ce of a	C-141 report	does not relieve th	e operator	at to grout r of respon	na water nsibility	for compliance
with any othe	r federal, st	ate, or local la	aws,and/o	regulations.					. от гозро		ior compilation
() ()						OIL CONSERVATION DIVISION					
Signature: Low Zunky						- low-son					
Printed Name: Don Embrey						Approved by District MANNENTAL ENGINEER					
1											
Title: Adviso	<u>r</u>		Approval Dat	e: 7.8.08	Ex	piration I	Date: Q	.8.08			
E-mail Address: dembrey@targaresources.com							Conditions of Approval:				
	. demore	, with gai cool					• •			Attack	ned 🗌
Date: 4/01/0				688-0546	SUBMI	T DEU NE	ATION	力	11	RP 1893	
Attach Additional Sheets If Necessary WORKPAN BY											