<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr , Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action												
Y.						<b>OPERAT</b>				al Report	X Final Repo	
Name of Co	Where USA Mineral Owner State of New Mexico Lease No. API 30-025-27783  LOCATION OF RELEASE  Section Township Range Feet from the North/South Line Feet from the East/West Line County											
Address	Facility Name Richardson Unit #1 Facility Type											
Facility Name Richardson Unit #1 Facility Type												
Surface Owner USA Mineral Owner State of New Mexico Lease No. API 30-025-27783												
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/W	est Line	County		
М	32	13S	36E	660'	S		660'	W		Lea		
	.,		Lat	titude		Longitud	e				AR 10	
				NAT	URE	OF RELI	EASE	- (*		· ·	77.	
Type of Release - 123 bbls of condensate Volume of Release 123 bbls Volume Recovered 6 bbls												
Source of Release Date/Hour of Release 4/22/08 4pm Date/Hour Discovered 4/23/08 2:30 pm Was Immediate Notice Given? If YES, To Whom?												
Was Immediate Notice Given?  Yes No Not Required If YES, To Whom?  Larry Johnson w/Hobbs OCD												
Ry Whom?	Whom? Keith Cannon  Date and Hour 3:00 pm  as a Watercourse Reached?  If YES, Volume Impacting the Watercourse.											
☐ Yes 🔀 No							RECENE					
If a Watercourse was Impacted, Describe Fully.*												
APR 2.5.2009												
Describe Cause of Problem and Remedial Action Taken.*												
3" load line valve was not sealed and cow kicked it partially open. Fluid stayed on lease road and location.												
Describe Area Affected and Cleanup Action Taken.*												
Remediation clean-up, sprayed 500 gallons 3% microblaze work completed by mid-day on the 4/24/08.												
	2DENZ					1					- CD - 1	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
				tance of a C-141	report do	es not relieve	e the operator of i	responsit	oility for co	ompliance wi	th any other	
federal, state,	or local lav	vs and/or regu	ilations.			·	OH COM	anni	ATTONI	DHUGIO		
		(I) \	$\smile \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \!$	! )			OIL CON	SER V	ATION	DIVISIO	<u>N</u>	
Signature: any K. Jick							I ohnson					
Printed Name: Tammy Link							Approved by District Supervisor:					
						ENVIRONMENTAL ENGINEER						
Title: Engir	neering Te	cn			<i>P</i>	Approval Dat	e: 4.28.09	B E	xpiration l	Date:		
E-mail Address: tlink@heycoenergy.com						Conditions of Approval:					П	
Date: 4/24/	08		· Phone:	(505)623-6601	-				•	129	1847	
Attach Addit	ional Shee	ts If Necess										

FORLO827041427

ADDITION SAMPLING REQUIRED TO DETERMINE VERTICAL -NEED PLAT OF SPILL AREA & # OF SOFT.