

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30.025-06974

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name Stephens & Johnson Operating Co.	Contact Bob Gilmore
Address P.O. Box 2249 Wichita Falls, Texas 76307-2249	Telephone No. [940] 723-2166
Facility Name J. N. Carson	Facility Type Oil well

Surface Owner City of Euice	Mineral Owner	Lease No.
--------------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 33	Township 21S	Range 37E	Feet from the 1320	North/South Line North	Feet from the 1800	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude N32 deg 26.245' Longitude W103 deg 09.987'

NATURE OF RELEASE

Type of Release Oil, Water - Gas	Volume of Release .5 Bbl	Volume Recovered 0 Bbls.
Source of Release Flowline Leak	Date and Hour of Occurrence 5-7-08 8:00 PM	Date and Hour of Discovery 5-7-08 8:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? State Hwy Trooper	
By Whom? Mike Petrek	Date and Hour 5-7-08 8:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. *

Describe Cause of Problem and Remedial Action Taken. *

Flowline leak @ N 19th & Ave J in Eunice, NM. Turned well off, picked up fluid from street. Flushed line with fresh water.

Describe Area Affected and Cleanup Action Taken. *

Affected area was on pavement. Plan to dig up leak. Replace bad spot in flowline. Dig up any contaminated soil. Repair street.

WAS REPAIRED - HIGHLANDER STAMPED - AREA IS CLEAN - 89

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Bob Gilmore	Approved by: District Supervisor ENVIRONMENTAL ENGINEER	
Title: Petroleum Engineer	Approval Date: 6-27-08	Expiration Date:
E-mail Address:	Conditions of Approval:	
Date: 5-14-08 Phone: [940] 723-2166	IRP# 1885 Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary