

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: Rice Operating Company	Contact: Jennifer Johnson
Address: 122 West Taylor	Telephone No.: 505-393-9174
Facility Name: EME	Facility Type: SWD Gathering line

Surface Owner: State	Mineral Owner:	Lease No.:
----------------------	----------------	------------

**LOCATION OF RELEASE** API# 30.025.05721.00.00

Unit Letter F	Section 29	Township 19s	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude: 32\*37.913N Longitude: 103\*16.529W

**NATURE OF RELEASE**

Type of Release: produced water with oil	Volume of Release: 100	Volume Recovered: 20
Source of Release: Pipeline	Date and Hour of Occurrence: 12/29/05	Date and Hour of Discovery: 12/29/05 11:55 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Paul Sheeley	
By Whom? Jennifer Johnson	Date and Hour: 4:00 pm 12/29/05	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* 6" A/C line cracked, replaced with 20' of 6" PVC line.

Describe Area Affected and Cleanup Action Taken.\* 5371 sq ft affected. The top 7" of impacted soil was hauled to a NMOCD approved disposal facility. Chloride concentrations show a conclusive decline with depth, indicative of non saturated vadose zone conditions. ROC concludes that with restoration of surface vegetation no further action is warranted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Johnson</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jennifer Johnson		Approved by District Supervisor: <i>Chris Williams</i>	
Title: Environmental and Field Technician		Approval Date: 6/22/07	Expiration Date:
E-mail Address: jjriceswd@valornet.com		Conditions of Approval:	
Date: 8/01/06 Phone: 505-393-9174		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

FGRL0834534508

IRP-2023