District I	f New Mexico	, .	Form C 141	
District II <u>District II</u> <u>State of New Mexico</u> <u>District II</u> <u>State of New Mexico</u> <u>Energy Minerals and Natural Resources</u>		Form C-141 Revised October 10, 2003		
APR 0 8 2009 Oil Conservation Division		Submit 2 Copies to appropriate District Office in accordance		
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505			with Rule 116 on back	
1220 S. St. Francis Dr., Santa Fe, NM 87505 Concerned Santa	Fe, NM 87505		side of form	
<b>Release Notification and Corrective Action</b>				
	OPERATOR	🔀 Initial	Report Final Report	
Name of Company ConocoPhillips Company Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Contact Jesse A. Sosa	126		
Facility Name SEMU Strawn Battery	Facility Type Battery - Ser			
Surface Owner ConocoPhillips Mineral Owner	·MLM	Lease N	Lease No.	
LOCATION OF RELEASE				
	th/South Line   Feet from the	East/West Line	County	
G 25 20s 37e			Lea	
		JO NEARB	Y SEMU 167	
Latitude 1932 32,710 Longitude 03103 12,333				
Type of Release Oil	E OF RELEASE Volume of Release 19 bbls	Volume P	acovered 15 bblg	
Source of Release broken sight glass		bls Volume Recovered 15 bbls rence8 am 3/Dat#09nd Hour of Discovery 8:30 am		
Was Immediate Notice Given?	If YES, To Whom? NMOCD & BLM			
By Whom? Jesse Sosa				
By whom? Jesse Sosa	Date and Hour 04/02/2009 3:45 pm			
Yes X No				
If a Watercourse was Impacted, Describe Fully.*				
WATER (9)65'				
	- 1941 - N	مر من المر من م	ана ала ала ала ала ала ала ала ала ала	
Describe Cause of Problem and Remedial Action Taken.*				
A hydrocarbon release ocurred due to a broken sight glass. Separator was shut in and isolated.				
Describe Area Affected and Cleanup Action Taken.*				
Affected area was 20 feet X 55 feet, all on caliche pad at battery. Site will be cleaned up removing soil and replaceing with fresh soil.				
I hereby certify that the information given above is true and complete t	o the best of my knowledge and	understand that purs	uant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger				
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health				
or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	t does not relieve the operator of	f responsibility for co	ompliance with any other	
	OIL CONSERVATION DIVISION			
Signature:				
Printed Name: Jesse A. Sosa	Approved by District Supervi		Solemy	
Title: HSER Lead	Approval Date: 04/10/0	9 Expiration	Date: 06/09/09	
E-mail Address: Jesse. A. Sosa@conocophillips.com	Conditions of Approval: DEL CLEAN +1 PER NMOCD	QUIDELINES.	Attached	
Date: 04/02/2009 Phone: (505)391-3126	FINAL C-141 DVE 06	109109	189-09.4.2151	
* Attach Additional Sheets If Necessary		*		

\_\_\_\_\_

4.74

-----

FARL 0910038488

and the second s

- produce allowing to be and the second pro-

سينس بينام اليب

.....

.....