District I 1625 N French District II 1301 W Grand District III 1000 Rio Brazos District IV 1220 S St. Fran	Avenue, Arte	nerals Conser South	f New Mexico s and Natural Resources ervation Division th St. Francis Dr. Fe, NM 87505			Form C-141 Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form							
							orrective A	ction	1				
OPERATO										al Report		Final Report	
							Contact Kanicia Carrillo						
Address 55 Facility Nar		Telephone f Facility Typ	No. 432-685-43 pe- Battery	32									
Surface Owner BLM Mineral Owner Lease No.API# 30-025-34773												54775	
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
F	21	175	32E	2160	L.,	North	2310		West	<u> </u>	Lea	1	
Latitude Longitude													
NATURE OF RELEASE Type of Release- Oil & Produced water Volume of Release-8 bbls oil, 10 Volume Recovered- 0 bbls													
								·	Dete and Hour of Discourse				
Source of Release- 1" gas line							Date and Hour of Occurrence- 04/06/09-1:55pmDate and Hour of Discovery 04/06/09-1:55 pm					/	
Was Immediate Notice Given?							If YES, To Whom? d Larry Johnson w/OCD & Trish Badbear w/BLM.						
By Whom? Pat Ellis Date and							Date and Hour April 6,2009, 6:00pm.						
Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Yes 3 X No If YES, Volume Impacting the Watercourse.													
If a Watercourse was Impacted, Describe Fully.*													
WATEROII5													
Describe Cause of Problem and Remedial Action Taken.*													
We believe the 1" gas line coming into to volume pot had pulled out of the 90 right at the inlet to the pot. The threads on both the nipple and the 90 looked worn and flat. So, the 1" gas line would have been blowing almost directly into the burner of the 6' heater. Witnesses say the 6' foot heater was the first burning vessel. The fire department was there to put out the fire.													
Describe Area Affected and Cleanup Action Taken.*													
The area affected was the battery pad 20 yards x 20 w/ an area 20 yards x 40 yards in the pasture behind the battery. We picked up the saturated soil and Tetra Tech Environmental will take soil samples to delineate the contamination. Tetra Tech will turn in soil samples and final report.													
regulations al public health should their o or the environ	Il operators or the enviro operations h nment. In a	are required t ronment. The nave failed to a	o report an acceptanc adequately OCD accep	nd/or file certain r ce of a C-141 report investigate and r	elease n ort by th emediat	otifications a e NMOCD m e contaminati	knowledge and u nd perform correc parked as "Final Re ion that pose a thre ye the operator of r	tive act eport" d eat to gi	ions for rel- loes not reli round water	eases which ieve the ope r, surface wa	may e rator o ater, hu	endanger of liability uman health	
	12.	OIL CONSERVATION DIVISION											
Signature:						Approved by District Supervisor: Healthour Lakeme							
Printed Name: Kanicia Carrillo													
Title: Regula	atory Analy	st		Approval Dat	te: 05/01/09		Expiration	Date: 66/2	00	q			
		arrillo@conch	s com		7								
					Conditions of Approval SUBMIT				Attached		2118		
Date: 04/16/ * Attach Addit	tional Shee	ets If Necess					<u> </u>			11117-05	1.2	- 2168	
	F GI	RL Dalz	15654	ίī -									