

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

MAY 01 2009

HOBBSOCD

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	Ramsey W.A. NCTD	Facility Type	Oil Storage

Surface Owner	STATE	Mineral Owner		Lease No.	283427
---------------	-------	---------------	--	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	28	24s	38e					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Hydrocarbon(Oil)	Volume of Release	6 bbls	Volume Recovered	4 bbls
Source of Release	Valve knocked open	Date and Hour of Occurrence	4/9/09 12:00 am	Date and Hour of Discovery	4/9/09 8:00 am
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Buddy Hill		
By Whom?	Dusty Wilson	Date and Hour	4/14/09 @ 2.00 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully *

N/A

WATER @ 22.5'



Describe Cause of Problem and Remedial Action Taken.*

High winds caused sign at lease to fall over and hit release valve, cracking the valve open. Spill affected a 30' X 10' area on location. NMOCD(Jeff Leking) was contacted 4/30/09 at 8:50 am, and advised of soil test results taken from the spill site. Remediation efforts will consist of removal of top 3" of impacted soil, to be hauled to Sundance Services for disposal, and backfilled with clean, like , materials, as per the conversation with NMOCD Representative Leking. Copies of lab results will be sent to NMOCD with the initial C-141.

Describe Area Affected and Cleanup Action Taken.*

Remediate to NMOCD Requirements. Listed Above.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson	Approved by: ENV ENGINEER District Supervisor 	
Title: HES Specialist	Approval Date: 05/08/09	Expiration Date: 07/07/09
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval: SUBMIT FINAL C-141 BY	Attached <input type="checkbox"/>
Date: 4/30/09	Phone: (575) 397-8210	IRP-09-5-2175

• Attach Additional Sheets If Necessary

AGRL0912842567



PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
BBC INTERNATIONAL, INC.
ATTN: CLIFF BRUNSON
P.O. BOX 805
HOBBS, NM 88241
FAX TO: (575) 397-0397

Receiving Date: 04/17/09
Reporting Date: 04/23/09
Project Owner: OXY
Project Name: RAMSEY WA NCTD
Project Location: JAL, NM

Sampling Date: 04/16/09
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: TR
Analyzed By: AB/ZL

LAB NO.	SAMPLE ID	GRO (C ₈ -C ₁₀) (mg/kg)	DRO (>C ₁₀ -C ₂₈) (mg/kg)	BENZENE (mg/kg)	TOLUENE (mg/kg)	ETHYL BENZENE (mg/kg)	TOTAL XYLENES (mg/kg)
ANALYSIS DATE:		04/21/09	04/21/09	04/22/09	04/22/09	04/22/09	04/22/09
H17273-1	SP1 3-4"	323	1,290	<0.050	1.04	1.89	5.45
H17273-2	SP2 3-4"	104	457	<0.050	0.069	0.254	1.29
Quality Control		545	541	0.048	0.045	0.048	0.158
True Value QC		500	500	0.100	0.100	0.100	0.300
% Recovery		109	108	98.0	90.0	96.0	105
Relative Percent Difference		8.8	10.9	1.4	1.4	2.4	15.5

METHODS: TPH GRO & DRO - EPA SW-846 8015 M; BTEX - SW-846 8021B.

TEXAS NELAP ACCREDITATION T104704398-08-TX FOR BENZENE, TOLUENE, ETHYL BENZENE,
AND TOTAL XYLENES.

Lab Director

Date

H17273 BTEX0015 BBC

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

RECEIVED



CARDINAL LABORATORIES






101 East Marland, Hobbs, NM 88240

(505) 393-2326 FAX (505) 393-2476

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Company Name: BBC International, Inc.				ANALYSIS REQUEST			
Project Manager: Cliff Brunson				P.O. #:			
Address: P.O. Box 805				Company:			
City: Hobbs		State: NM Zip: 88241		Attn: SAME			
Phone #: 575-397-6388		Fax #: 575-397-0397		Address: SAME			
Project #:		Project Owner: Oxy		City: SAME			
Project Name: Ramsey WA NCTD				State: Zip:			
Project Location: Jal, NM				Phone #:			
Sampler Name: Amy C. Ruth				Fax #:			
FOR LAB USE ONLY							
Lab I.D.	Sample I.D.	GRAB OR (COMP. # CONTAINERS)	MATRIX	PRESERV.	SAMPLING		
			GROUNDWATER				
			WASTEWATER				
			SOIL				
			OIL				
			SLUDGE				
			OTHER:				
			ACID/BASE				
			ICE/COOL				
			OTHER:				
				DATE	TIME		
117273-1	SP1 3-4"	G			4-16-09 1030	TPH (GRAB/DRO) 8015 M	
-2	SP2 3-4"	G			4-16-09 1035	BTX	

PLEASE NOTE: Liability and Damages. Governor's liability and claims exclusive remedy to any claim arising where based in contract or tort, shall be limited to the amount paid by the client to the analysts. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors. ~~IN NO EVENT SHALL CARDINAL BE LIABLE FOR THE PERFORMANCE OF SERVICES HEREUNDER BY CARDINAL, INCLUDING THOSE WHICH ARE BASED UPON ANY OF THE ABOVE STATED REASONS OR OTHERWISE.~~

Relinquished By: 		Date: _____ Time: _____		Received By: 		Phone Result: <input type="checkbox"/> Yes <input type="checkbox"/> No Add'l Phone #: _____ Fax Result: <input type="checkbox"/> Yes <input type="checkbox"/> No Add'l Fax #: _____ REMARKS: _____	
Relinquished By: 		Date: 7/17/05 Time: 5:12 p		Received By: 			
Delivered By: (Circle One) Sampler - UPS - Bus - Other: _____				Sample Condition Cool Heat <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> No		CHECKED BY: (Initials) 	

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476